

## The Standard PROPELLER LOG

ASA-SP-L

Propeller Record General Information		akt was reason as	Man and the second
- Har Manufacturer HXRTZECC	applications of the second	Period Three	
Propeller Manufacturer HXPT26U  Model HCE24L-2UBS  Hub Series # B91933	Туре		The same
Hub Series # 139 1933	Blade #	T STATE CONTY	
Date of Manufacture	And the manufacture of the second	elipsymistry eliterate in stage	0+10409786788
		Chiana area	Control of the second
			de la
		Supering to	12 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
Aircraft Installed On:  Make/Model  PA-30 W8/734  TUGHT SIDE	Serial #	287	
101911 SIPE			
		P. Laker	
	THE RESERVE OF STREET STREET,	A ME COLUM	

## VALLEY PROPELLER SERVICE INC. SERVICEABLE PARTS TAG

REMARKS

Date:

**Next Inspection** Time Since Due:

Overhaul

Mech. Cert. # or Repair Station #

/ear:	Total Time in Service
Next Inspection	Time Since
Due:	Overhaul
/ear:	Total Time in Service
lext Inspection	Time Since
Due:	Overhaul
/ear:	Total Time in Service
Next Inspection	Time Since
Due:	Overhaul

## SkyView Aviation

SkyView Aviation, LLC 5749 South Tracy Blvd Tracy CA 95377 (209)830-7666 DNS [

N Number: N8173Y

L Tach: 669.7

Smoh: 775.7

Prop.TT: 5320.2 right

Complied with Annual inspection in accordance with CFR 43 appendix"D". See recurring AD compliance record dated 01/04/2021 and old aircraft records for AD information. Removed propeller and installed new Generator belt P/N 37B197774-341. Re-installed propeller. I certify that this Propeller has been inspected in accordance with an Annual inspection and was determined to be in airworthy condition.

Richard Ortenheim A&P 2517877 IA

Date: 02/20/2021

Mur Lanco

Next Inspection Due:	Time Since Overhaul	Mech. Cert. # or Repair Station #		
Date:				
Year:	Total Time in Service	Description	All the state of	Contract the second
		Mech. Cert. # or Repair Station #		
Next Inspection Due:	Time Since Overhaul			us sit estilf a notine band to
Date:	12/19/34	· 医多种性 医克里特氏 医克里特氏病 医克里氏病 医克里氏病 医克里氏病 医克里氏病 医克里氏病 医克里氏病 医克里特氏病 医克里特氏病 医克里特氏病 医克里特氏病 医克里氏病 医克里氏病 医克里氏病 医克里氏病 医克里氏病 医克里氏病 医克里特氏病 医克里氏病 医克里特氏病 医克里氏病 医克里氏病 医克里氏病 医克里氏病 医克里氏病 医克里氏病 医克里氏病 医克里氏病 医克克氏病 医克克克氏病 医克克氏病 医克克克克氏病 医克克克氏病 医克克克氏病 医克克克氏病 医克克氏病 医克克氏病 医克克克氏病 医克克氏病 医克克克氏病 医克克氏病 医克克克氏病 医克克氏病 医克克克氏病 医克克克氏病 医克克克氏病 医克克克氏病 医克克克氏原生原生原生原生原生原生原生原生原生原生原生原生原生原生原生原生原生原生		
is approved for i	return to service. I	ne, propeller or appliance identified above was repaired an ertinent details of the repair(s) are on file at this Facility un	Signature:  Huy Bui 3688325	
N propeller has	been inspected i	n IAW Piper PA30 Maintenance Manual & Multi E n accordance with a 100 HR/Annual inspection an	d determined airworthy this date.	
RH-S/N: B91	14 (2 25 26 25 )	7220 S. 4450 W. Jordan, UT 8 801-755-539	TSPOH: 808.8	
Model: HC-E	Make: Hartzell  Model: HC-E2YL-2LBS  Advantage Aviation  South Valley Regional Airport		W/O: LH Tach: 702.8	

