

RIGHT

R

Propeller Logbook



SENENICH PROPELLER SERVICE, INC.



- McCauley
- Hartzell
- MT
- Sensenich
- Dowty
- Hamilton Standard

INSTALLING AGENCY PLEASE NOTE:
Recording of Propeller Total Time Since New (TTSN)
is Required Per F.A.R. 91.417

Lancaster Airport, 519 East Airport Road, Lititz, PA 17543 (800) 462-3412 (717) 560-3711 Fax: (717) 560-4354 FAA Certified Repair Station #QV9R194N

Lee Gilmore Memorial Airport, 1142 Aviation Boulevard, Gainesville, GA 30501 (800) 791-7767 (770) 538-0444 Fax: (770) 538-0117 FAA Certified Repair Station #S46R346N

Windham County Airport, 21 Airport Road, North Windham, CT 06256 (877) 456-7944 (860) 456-7944 Fax: (860) 456-0410 FAA Certified Repair Station #Q0PR011X

1. Approving National Aviation Authority/Country: FAA / UNITED STATES	2.	AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG	3. Form tracking Number: 11-0147
---	----	--	---


4. Organization Name and Address: Sensenich Propeller Service, Inc 1142 Aviation Boulevard, Gainesville, Ga. 30501	5. Work Order/Contract/Invoice Number: G14742
---	--

6. Item:	7. Description:	8. Part Number:	9. Eligibility: *	10. Quantity:	11. Serial/Batch Number	12. Status/Work:
1	Hartzell 4-Blade Propeller Assembly	HC-C4YR-2/ FC7663D-6Q	TBV	1	FH45	Overhaul

13. Remarks: Blade S/N's: E26873, E25326, E25316, E25312. Manuals: 117D R-14, 133C R-26 & 202A. Comply with S/Bs: Thru 326, S/Ls: Thru 319, S/Is: Thru 206, S/As: Thru 52. All work done in accordance with Hartzell Specifications.

Propeller TSN: **Brought Forward** Propeller TSO: **-0-**

14. Certifies the items above were manufactured in conformity to: <input type="checkbox"/> Approved design data and are in condition for safe operation. <input type="checkbox"/> Non-approved design data specified in Block 13.	19. <input checked="" type="checkbox"/> 14 CFR 43.9 Return to Service <input type="checkbox"/> Other regulation specified in Block 13. Certifies that unless otherwise specified in Block 13, the work identified in Block 12 and described in block 13 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.
---	--

15. Authorized Signature:	16. Approval/Authorization No.:	20. Authorized Signature: 	21. Approval/Certificate No.: S46R346N
17. Name (Typed or Printed):	18. Date (m/d/y):	22. Name (Typed or Printed): Daniel Landis	23. Date (m/d/y): 3/31/11

USER/INSTALLER RESPONSIBILITIES

It is important to understand the existence of this document alone does not automatically constitute authority to install the part/component/assembly. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness accepts parts/components/assemblies from the airworthiness authority of the country specified in Block 1. Statements in Blocks 14 and 19 do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft can be flown.

SERVICE I

RT Propeller Log N6598L

Page 1 of 1

2/10/2018

Hobbs 1701.9

Heart of Virginia Aviation
11152 Airpark Rd
Ashland, VA 23005



Phone: 804-798-6500
Fax: 804-798-6544

Tach: 2348.3 Right Prop TT: 1853 TSO: 45.2
N6958L

Jan 2, 2015

I certify this Prop has been inspected in accordance with a 100 hour inspection and was determined to be in airworthy condition.

Daniel Mcsherry AP3110300

Heart of Virginia Aviation
11152 Airpark Rd
Ashland, VA 23005



Phone: 804-798-6500
Fax: 804-798-6544

Hobbs: 1391.46 RPTT: 1996.26 TSO: 188.46
N6598L

Feb 3, 2016

I certify this Prop has been inspected in accordance with a 100 hour inspection and was determined to be in airworthy condition.

Ronald L. Hawkins AP2705318

Heart of Virginia Aviation
11152 Airpark Rd
Ashland, VA 23005



Phone: 804-798-6500
Fax: 804-798-6544

Hobbs: 1606.00 RPTT: 2210.0 TSO: 403.00
N6598L


Feb 3, 2016

I certify this Prop has been inspected in accordance with a 100 hour inspection and was determined to be in airworthy condition.

Ronald L. Hawkins AP2705318

1. Lubricated and dressed blades as needed.

This propeller has been inspected IAW an Annual Inspection and was found airworthy on this date.

Inspector:  Certificate #AP2636560 IA
Allen Campbell

RT Propeller Log

N6598L

Page 1 of 1


5/27/2020

PTSO 1

Hobbs 1773.0

Lubricated and dressed blades as needed.

This propeller has been inspected IAW an Annual Inspection and was found airworthy on this date.

Inspector:  Certificate #AP2636560 IA
Allen Campbell

RT Propeller


N6598L

Page 1 of 1

8/12/2020

Hobbs 1817.8

Removed this propeller from N6598L.

Inspector:  Certificate #AP2636560 IA
Allen Campbell

PROP MODE (R)
HC-C4YR-2
PROP S/N (R): FH45
REG. NO: N6598L
WORK ORDER: 22267



Aerodyne Corporation

Repair Station No. HO1R-199K
5198 West Military Highway
Chesapeake, VA 23321 USA
Phone: (757) 488-2898

HISTORY

DATE: 3/4/2019
A/C TSN: 4620.5
PROP TT (R): 2330.6
TSPOH (R): 522.8
HOBBS: 1745.7

Date	Description of Work	Authorized Signatures
	<p>Right Prop Entries</p> <p>(5) Completed right propeller 100 hour inspection in accordance with the manufacturer's recommendations and a checklist conforming to Title 14 Code of Federal Regulations Chapter 43 Appendix D. Denicked blades. Serviced propeller hub with Aeroshell No. 6 grease.</p>	
	<p>The article identified hereon was inspected in accordance with a 100 Hour Inspection, found to be in an airworthy condition and approved for return to service.</p>	
DATE: 3/4/2019	SIGNED: <i>J.R. Smith</i>	
	J.R. Smith Certified Repair Station No. HO1R-199K	Work Order: 22267
	Printed by EBis 3 (datcomedia.com)	





Date: August 28, 2020
Propeller model: HC-C4YR-2 Serial number: FH45
Disassembled, cleaned, and visually inspected for grease leak. Assembled using new seals. Set blade angles and checked track and static balance. This was the only work done. See form 8130-3 for details.

MAINTENANCE RELEASE: The component identified above was repaired and inspected in accordance with regulations of the FAA and was found airworthy for return to service for the work performed. Pertinent details of the repair are on file at this agency under work order number: ER-14344

Approved by: *Shawn M. Young*
Shawn M. Young 2747920 Repairman for:

East Coast Propeller Service, Inc.
2079 Main Street
Lititz, PA 17543 Phone: 1-800-875-6377
email: eastcoastprop@dejazzd.com
FAA Repair Station E65R064Y/ EASA.145.6298

SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description of Work	Authorized Signatures
RT Propeller Log	N6598L	Page 1 of 1		
4/1/2024	PTSO 864.0	Hobbs 2067.0		
Lubricated and dressed blades as needed.				
This propeller has been inspected IAW an Annual Inspection and was found airworthy on this date.				
Inspector:  Certificate #AP2636560 IA				
Allen Campbell				
RT Propeller Log	N6598L	Page 1 of 1		
04/27/2025	PTSO 921.3	Hobbs 2124.3		
Lubricated and dressed blades as needed.				
This propeller has been inspected IAW an Annual Inspection and was found airworthy on this date.				
Inspector:  Certificate #AP2636560 IA				
Allen Campbell				



SENENICH PROPELLER SERVICE, INC.

www.senenichpropellers.com

