Instructions for the Use of Log Book

1. This log must always accompany the aircraft to which it refers.
2. No pages shall be torn from Log Book. No erasures, and all entries to be made in ink.
3. Original entries shall be made and signed by manufacturer or seller. All other entries shall be made by Pilot, Owner, Mechanic, or other competent person authorized to do so.
4. On journey, the pilot is responsible for keeping Log Book and entries or omissions therein. Failure to do so will be considered a serious neglect of duty.
5. Before departure on journey, pilot is personally to ascertain that entries in log have been made are correct, and then sign certificate to the effect.
6. Special data such as manufacturers notes, test data, reconditioning, etc., should be affixed to stubs provided for that purpose in the back of this book.
7. CAA 1-1 Repair and Alteration forms listed on last page.
8. This log book shall be available and produced, on demand, to anyone so authorized.

Book 1.

PIPER AIRCRAFT CORP.—LOCK HAVEN, PA., U. S. A.

AIRCRAFT LOG

N 84064
License No.

Aircraft Name Piper Model PA-30 Serial No. 30-1556

Engine Name Lycoming Model O-320-B1A(2) Serial No. RL-3319-55A RL-3325-55A

Description of Aircraft Color: White/Red & Gold/Black T.C. No. A1EA

4 place Cabin Land Monoplane

Date of Manufacture

Seating Capacity (including pilot) 4 Wt. Empty 2362 Gross Wt. 3600

Make of Propeller Hartzell Hub Design No. HC-E2YL-2B Hub Serial RL-BG-3240 RL-BG-3237

Blade Design No. 766314 Blade Serial Nos. (Lt.) B1229 B1241 (Rt.) B1209 B1201

Owner

Address

Transferred to Date

NOTICE:- Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by ... by Civil ... ty.

NC .....

Date Year 1940 Mo.	Day	Time in Air Hrs.	Min.	Passengers Carried	NATURE OF FLIGHT
11	1	2	30		on delivery C38
11	3	3	25		
11	4	1	00		
11	8		50		
12	7	2	00		
12	30	8	00		
1	11	1	10		
1	23	2	30		
1	31	7	00		
2	1	2	20		
2	4		50		
2	7	1	55		
2	20	3	50		
Total Forward		37	20		

Place of Last Airplane Overhaul .....

Date of Last Overhaul .....

NOTICE.—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

AIRCRAFT LOG

REMARKS	SIGNATURE
I have inspected this aircraft and found it complies with the requirements of F.A.R 21.183. Certificate of Airworthiness dated 9-14-67 was issued by me. Lawrence Ahlgren Piper Aircraft Corporation D.O.A. No. EA-1	

NOTICE:--Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil [illegible].

N C .....

Date Year 1968 Mo. Day	Time in Air Hrs.	Min.	Passengers Carried	NATURE OF FLIGHT
	37	20		
2 24	2	05		
2 26		45		
5 8	9	30		
5 25	2	30		
5 27	2	20		
5 30	7	15		
6 25	8	45		
7 11	8	30		
7 15	7	10		
7 16	5	30		
7 19	1	20		
7 25	1	50		
7 26	1	15		
Total Forward	96	05		

Place of Last Airplane Overhaul .....

Date of Last Overhaul .....

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

AIRCRAFT LOG

REMARKS	SIGNATURE
The altimeter and ~~static system tests re-~~ quired by FAR Part 91.170 ~~have been per-~~ formed. The altimeter ~~has been tested to~~ 25,000 ft. Date 9-14-67 Signed Louis C. Hurst ~~Keystone Instruments, Inc.~~ ~~FAA Repair Station No. 1040~~ ~~Instrument Class 1 and Limited~~	

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Pen[illegible]ON

N C .....

Date Year Mo.	Day	Time in Air Hrs.	Min.	Passengers Carried		NATURE OF FLIGHT
1961		96	05			
7	27	0	50			
7	31	2	40			
8	14	13	00			
8	18	7	00			
8	20	6	00			
8	28	4	00	129	35	
9	4	3	40	133	15	
	5	2	00	135	15	
	7	2	00	137	15	
	8		45	138	00	
	9	2	00	140	00	
	11	1	25	141	25	
	12	2	10	143	35	
Total Forward						

Place of Last Airplane Overhaul .....

Date of Last Overhaul .....

TICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

AIRCRAFT LOG

REMARKS	SIGNATURE
18 June 1968 TT 68.00 I Certify that this A/C has been a 50 Hour Insp. and found in Greased A/C as per Chart 1 Greased L/G Replaced Exhaust Inspected Brake Lining. Serviced Battery Serviced Hydraulic Reserv Replaced Rt. Wing Nav. Lite Reflector. Main Gear Re-Traction A&P #1490133 William K. Shultz	Inspected A/W/W Authority Conducted

3

NOTICE:--Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

N C .....

Date Year ..... Mo.	Day	Time in Air Hrs.	Min.	Passengers Carried	NATURE OF FLIGHT
				143	35
9	15	1	00	144	35
	16	2	20	146	55
	18	6	05	153	00
	19	2	00	155	00
	20	2	10	157	10
	21	3	10	160	20
	22	1	15	161	35
	24	3	35	165	10
	25	1	05	166	15
	26	2	15	168	30
	27	2	05	170	35
10	1	1	05	171	40
	3		35	172	15
Total Forward					

Place of Last Airplane Overhaul .....

Date of Last Overhaul .....

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

AIRCRAFT LOG

REMARKS	SIGNATURE
25 July 1968 T.T. 100.00	
I C.E.R.T. that this A/C. has been inspected	inspected
1/12/at. & annual inspection and found to be in	found to be in
airworthy Condition	
Dressed A/C	
Dressed L/G	
Packed Wheel Bearings	
Serviced Shock struts (Nitrogen)	
Serviced Batteries	
Rem. Chem. Retarders	
No A.D.'s on A/C	
I.A. # 1490133 William K. Schultz	

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

NC .....

Date Year ..... Mo.	Day	Time in Air Hrs.	Min.	Passengers Carried	NATURE OF FLIGHT
				172	15
10	6	1	00	173	15
	7	1	15	174	30
	8	1	25	175	55
	11	4	20	180	15
10	25	27	00	207	15
11	5	18	00	225	15
		[illegible]			
4/7	20	799	27		A. W.
4 13		804	59		
4 20		811	07		
4 27		819	27		
5 4		827	41		
5-11		830	44		
Total Forward					

Place of Last Airplane Overhaul .....

Date of Last Overhaul .....

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty

AIRCRAFT LOG

REMARKS	SIGNATURE
10-26-68 - Jacked aircraft & swung gear retraction test. Gear leaking gear oil. Tube pulled & bearing repacked. Replaced bow assy. adj. & connecting rod. Replace light bulb in cir. trunk. compt. on floor. Add water to battery. Replaced Rt. windshield. Tightened jam nut on elev. trim tab rod. All control & control surfaces inspected. & checked all lights. Time in service: 208. hrs.	"I certify that this aircraft has been inspected in accordance with a 100-hr. inspection and was determined to be in airworthy condition. William Paul McClung A&P-1433977 Mechanic Cert. No. INDUSTRIAL AVIATION CORP. Stewart Air Park Parkersburg, West Virginia

4

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty

N C .....

Date Year Mo. Day	Time in Air Hrs.	Min.	Passengers Carried	NATURE OF FLIGHT
5-18	84	60		Glt
5-21	85	12		
Total Forward				

Place of Last Airplane Overhaul .....

Date of Last Overhaul .....

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

AIRCRAFT LOG

REMARKS	SIGNATURE
I CERTIFY THAT THIS AIRCRAFT ENGINE HAS BEEN INSPECTED IN ACCORDANCE WITH A 100 HR INSPECTION AND WAS DETERMINED TO BE AIRWORTHY. SIG. Jerome A. Wood DATE JAN 18, 1969 TOTAL TIME 325.37 A&E 1618166	
I CERTIFY THAT THIS AIRCRAFT ENGINE HAS BEEN INSPECTED IN ACCORDANCE WITH A 100:00 INSPECTION AND WAS DETERMINED TO BE AIRWORTHY. SIG. [illegible] A+P IC 4105 DATE 4-30-69 TOTAL TIME 425.00	

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

AIRCRAFT LOG

REMARKS	SIGNATURE
I CERTIFY THAT THIS AIRCRAFT ~~ENGINE~~ HAS BEEN INSPECTED IN ACCORDANCE WITH A 100 HR INSPECTION AND WAS DETERMINED TO BE AIRWORTHY.	
SIG ~~Graeme A Wood~~ DATE ~~June 27, 1969~~	
TOTAL TIME 528.00 A&E 1618166	
VOR's CHECKED - O.K. 6/28/69 (528.0 HE)	DC Hennig 1466747 CFR
REMOVED & REPLACED FLAP MOTOR ASSY MODEL NO. 721082A OPERATION CHECK FLAP - GOOD DATE; JULY 2, 1969 TACH TIME; 532.00 A&E 1618166 Sig. Graeme A. Wood	

5

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penal

AIRCRAFT LOG

REMARKS	SIGNATURE
I CERTIFY THAT THIS AIRCRAFT ENGINE ~~HAS~~ BEEN INSPECTED IN ACCORDANCE WITH A 100 HR INSPECTION AND WAS DETERMINED TO BE AIRWORTHY.	CHECK PIPER CHECK SHEET FOR WORK ACCOMPLISHED
SIG Jerome A. Wood DATE August 22, 1969	
~~TOTAL~~ TOTAL TIME 550.63 AEE 1618166	

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

AIRCRAFT LOG

REMARKS	SIGNATURE
I certify that this Aircraft has been inspected for a Annual inspection as required by C.A.R. and determined to be airworthy. Total Time 150 Date 8-23-68 Mechanic C. E. Cloth AI 207603	

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

N C .....

Date Year ..... Mo. Day	Time in Air Hrs.	Min.	Passengers Carried	NATURE OF FLIGHT
4-13-70			804.59	LEFT WING
~~4-20-70~~			793.13	RIGHT
4 20 70			811.07	Left
			799.15	Right ICE
4-27-70			819.27	left
			807.70	right
5-4-70			827.43	
			815.88	
6-10	8		868.95	LEFT
			856.15	RIGHT BC VOR RECIEVER CHECK IN ACCORDANCE PART 91
6-11			872.97	LEFT WING
			860.06	RIGHT
6-12			913.40	Left Key
Total Forward			900.00	Right

Place of Last Airplane Overhaul .....

Date of Last Overhaul .....

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

AIRCRAFT LOG

REMARKS	SIGNATURE
I CERTIFY THAT THIS AIRCRAFT ENGINE HAS BEEN INSPECTED IN ACCORDANCE WITH A 100 HR. INSPECTION AND WAS DETERMINED TO BE AIRWORTHY. SIG. [signature] A&P 16400 DATE 11-11-69 TOTAL TIME 6 600.00 HRS	
I CERTIFY THAT THIS AIRCRAFT ENGINE HAS BEEN INSPECTED IN ACCORDANCE WITH A 100 HR. INSPECTION AND WAS DETERMINED TO BE AIRWORTHY. SIG. [signature] DATE FEB 5, 1970 TOTAL TIME 756.0 M-1537859 A+P	

8

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

AIRCRAFT LOG

REMARKS	SIGNATURE
I CERTIFY THAT THIS AIRCRAFT ENGINE HAS BEEN INSPECTED IN ACCORDANCE WITH A 100 HR. INSPECTION AND WAS DETERMINED TO BE AIRWORTHY. SIG Jerome A. Wood DATE 5-22-70 TOTAL TIME 847.00 HEE 1618166	
5-29-70 INSTALLED UGR-2 REMOVED VOA-4 + INSTALLED VOA-50 OMNI/GS HEAD SEE 337 DATED 5-29-70 FOR DETAILS M G Hutchinson	A+P IA #'s
5-29-70 FLT TESTED UGR-2 + VOA-50, OK FOR SERVICE M G Hutchinson	A/T #3000470 CFII

9

NOTICE:--Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

N C .....

Date Year Mo.	Date Day	Time in Air Hrs.	Time in Air Min.	Passengers Carried	NATURE OF FLIGHT
	70				
8	3	L 971	42	JE.	
		R 957	53	JE.	
8	10	961.	13	KE2	
8	29	969.	89	KE2	
9	3	983	93	KE2	
		969	89	KE2	
9	21	976.	67	KE2	
9	28	1007:	52	HWL	
10	10				VOR CHECKED INACCEPTABLE WITH FAR 91 D F Lemmy 10/10/70
10	24	L-1056	09		
~~10~~	~~25~~	R-1039	23	BB.	
10	25	L. 1062	52	BB.	
		R 1045	56		
Total Forward		1070.	61	KE	

Place of Last Airplane Overhaul .....

Date of Last Overhaul .....

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

AIRCRAFT LOG

REMARKS	SIGNATURE
REMOVED & REPLACED AUX FUEL TANK MICRO SWITCH. TACH TIME 889.98 . DATE 16-06-10 Graeme A. Wood AEA 1618166	
I CERTIFY THAT THIS AIRCRAFT ENGINE HAS BEEN INSPECTED IN ACCORDANCE WITH A 100 HR INSPECTION AND WAS DETERMINED TO BE AIRWORTHY. SIG. Graeme A. Wood DATE 15-7-10 TOTAL TIME 949.00 AEA 1618166	

10

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

NC .....

Date Year Mo.	Day	Time in Air Hrs.	Min.	Passengers Carried	NATURE OF FLIGHT
11	18	1091	08	B.B.	V.O.R. ACCURACY CHECK OK B. Beach
11	18	R 1073	47	B.B.	
12	4-20	1112		L	
12	4-20	1097		R	
12-21-70		1115	L		
[redacted]		1098	R		
12-28-70		1110	L		
		1094	R		
2-10-71		11 77.	88	Hwk	
Total Forward					

Place of Last Airplane Overhaul .....

Date of Last Overhaul .....

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

AIRCRAFT LOG

REMARKS	SIGNATURE
I CERTIFY THAT THIS AIRCRAFT ~~ENGINE~~ HAS BEEN INSPECTED IN ACCORDANCE WITH A 100 HR. + ANNUAL INSPECTION AND WAS DETERMINED TO BE AIRWORTHY. SIG Richard L Beatty DATE 9-2-70 TOTAL TIME 985.0 IA-1537859	
I CERTIFY THAT THE ALTIMETER AND STATIC SYSTEM TESTS REQUIRED BY FAR 91.170 HAS BEEN PERFORMED. THE ALTIMETER HAS BEEN TESTED TO 20,000 FEET. 10-16-70 SIGNED Theodore L. Ferns DATE 10-20-70 CERTIFICATE #A+P 1988034	10-20-70 TACH: 1052.0 INSTALLED OVERHAULED ALTIMETER BY DUCASSE INST. SHOP. SEE CARD IN BACK OF LOGS. INSTALLED NEW AIRSPEED INDICATOR Theodore L Ferns A+P 1988034

11

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

N C .....

Date Year Mo.	Day	Time in Air Hrs.	Min.	Passengers Carried	NATURE OF FLIGHT
1	1-71	1187.20		123	
6	16 71				
8	19 71	1357.13		BB	
8	18 71	1367.06		BB	
9	7-71	1383.32		Hw	
9	20 71	1392.		[illegible]	
11	71	1413		[illegible]	
Total Forward					

Place of Last Airplane Overhaul .....

Date of Last Overhaul .....

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

AIRCRAFT LOG

REMARKS	SIGNATURE
I CERTIFY THAT THIS AIRCRAFT ~~ENGINE~~ HAS BEEN INSPECTED IN ACCORDANCE WITH A 100.00 INSPECTION AND WAS DETERMINED TO BE AIRWORTHY. SIG. [signature] A&P 1604605 DATE 11-6-70 TOTAL TIME 1078.0 100 check OK a/c FAD TT 1145 - 1-17-71.	[signature] ATR 15 V 3 D 45 CFI

12

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

N C .....

Date Year Mo.	Day	Time in Air Hrs.	Min.	Passengers Carried	NATURE OF FLIGHT
12/6	71			1463	gl
12/13	71			1468	gl
12/20	71			1479	gl
12/27	71			1481	gl
1/3	72			1485	gl
1/10	72			1489	gl
1/24	72			1500	gl
1/31	72			1505	gl
1/14	72			1525	gl
6-9-71		11	1652		Vor Robinson Houston 180556 HA
Total Forward					

Place of Last Airplane Overhaul .....

Date of Last Overhaul .....

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

AIRCRAFT LOG

REMARKS	SIGNATURE
I CERTIFY THAT THIS AIRCRAFT ~~ENGINE~~ HAS BEEN INSPECTED IN ACCORDANCE WITH A 100 HR. INSPECTION AND WAS DETERMINED TO BE AIRWORTHY. SIG. Stillman J. Slaty DATE 1-29-71 ~~TOTAL TIME~~ 1158.41 M-1537859 A+P	
I CERTIFY THAT THIS AIRCRAFT ~~ENGINE~~ HAS BEEN INSPECTED IN ACCORDANCE WITH A 100 HR. INSPECTION AND WAS DETERMINED TO BE AIRWORTHY. SIG. Stillman J. Slaty DATE 4-30-71 TOTAL TIME 4258.9 HRS M-1537859 A+P	

13

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

N C .....

Date Year Mo.	Day	Time in Air Hrs.	Min.	Passengers Carried	NATURE OF FLIGHT
3/6	72			1543	gl
3/13	72			1549	gl
3/20	72			1551	gl
4-11-	72			1566	tr
4/17	72			1566	gl
9/4	72			1710	gl
9/11	72			1714	gl
9/18	72			1717	gl
9/25	72			1720	gl
10	2			1724	tr
10	9			1733	tr
Total Forward					

Place of Last Airplane Overhaul .....

Date of Last Overhaul .....

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

AIRCRAFT LOG

REMARKS	SIGNATURE
I CERTIFY THAT THIS AIRCRAFT [redacted] HAS BEEN INSPECTED IN ACCORDANCE WITH A 100 HR INSPECTION AND WAS DETERMINED TO BE AIRWORTHY. SIG. Jerome A. Wood DATE 8-11-71 TOTAL TIME 1357.0 IA-1618166 A&P	INSTALLED (1 ENT) EA ALTERNAE STATIC SYS. PIPER KIT # 756-901 IAW SKETCH "A" "B" Jerome A Wood IA-1618166 A&P TT. 1357.0 8-11-71
I CERTIFY THAT THIS AIRCRAFT [redacted] HAS BEEN INSPECTED IN ACCORDANCE WITH A ANNUAL INSPECTION AND WAS DETERMINED TO BE AIRWORTHY. SIG. Julian O'Slatt DATE 8-11-71 TOTAL TIME 1357.0 IA 1537859	

14

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

Date Year Mo.	Day	Time in Air Hrs.	Min.	Passengers Carried	NATURE OF FLIGHT
10	16			1246	I CERTIFY THAT THE ALTIMETER AND STATIC
10	23			1250	SYSTEM TESTS REQUIRED BY FAR 91.170 HAS
10	30			1253	BEEN PERFORMED. THE ALTIMETER HAS BEEN
11	6			1252	TESTED TO 20,000 FEET. 10-16-70
11	13			—	SIGNED Chester J Mayer DATE 8-24-71
11	20			1278	CERTIFICATE # 1586231 PP
11	27			1785	
12	4			1792	
12	11			1794	
12	18			1799	
1	2			1805	
1	17			1826	
1	22			1837	
Total Forward					

Place of Last Airplane Overhaul .....

Date of Last Overhaul .....

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

AIRCRAFT LOG

REMARKS	SIGNATURE
I CERTIFY THAT THIS AIRCRAFT [redacted] HAS BEEN INSPECTED IN ACCORDANCE WITH A 100 HR INSPECTION AND WAS DETERMINED TO BE AIRWORTHY. M-1522437 to SIG. [signature] DATE ~~3-19-71~~ 10-3-71 TOTAL TIME 1457.0	
REMOVED & REPLACED VACUUM PUMP. 200CC. (RT) T.T. 1487.0 [signature] M-1618164 IA.	

15

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

N C .....

Date Year 73 Mo.	Day	Time in Air Hrs.	Min.	Passengers Carried	NATURE OF FLIGHT
				1846	hr
1	27			1548	hr
2	5			1854	hr
2	10			1865	hr
2	19			1873	HT
3	12			1895	hr [illegible]
3	19			1[illegible]	hr [illegible]
3	26			1[illegible]8	hr [illegible]
4	2			1905	hr [illegible]
4	9			1943	
5	4			1958	hr
5	19			1976	P.D.
6	20			~~1976/1958~~	~~LE~~ .
6	25			1979/1957	LE
Total Forward					

Place of Last Airplane Overhaul .....

Date of Last Overhaul .....

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

AIRCRAFT LOG

REMARKS	SIGNATURE
I CERTIFY THAT THIS AIRCRAFT ENGINE HAS BEEN INSPECTED IN ACCORDANCE WITH A 100 HR INSPECTION AND WAS DETERMINED TO BE AIRWORTHY. SIG. [signature] DATE 4-13-72 MCH 1922437 A TOTAL TIME 1566.61	

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

N C .....

Date Year Mo.	Day	Time in Air Hrs.	Min.	Passengers Carried	NATURE OF FLIGHT
	72				
				1994/1972	TR
7-73	9			2003/1981	I CERTIFY THAT THIS AIRCRAFT ~~ENGINE~~ HAS
29-7	16			2024/2002	BEEN INSPECTED IN ACCORDANCE WITH A
72-7	23			2033/2011	100:00 INSPECTION AND WAS
73-7	30			2045/2023	DETERMINED TO BE AIRWORTHY.
F	6			2050/2028	SIG. [signature] A+P Mech DATE 8-3-72
8	13			2057/2035	
8	20			2139/2117	TOTAL TIME 1666.4
11	5			2160.	I CERTIFY THAT THIS AIRCRAFT ~~ENGINE~~ HAS
11	12			2186.	BEEN INSPECTED IN ACCORDANCE WITH A
11	18				ANNUAL INSPECTION AND WAS
					DETERMINED TO BE AIRWORTHY.
					SIG. [signature] DATE 8-12-72
Total Forward					TOTAL TIME 1685.82 HRS IA 1537859

Place of Last Airplane Overhaul .....

Date of Last Overhaul .....

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

AIRCRAFT LOG

REMARKS	SIGNATURE
I CERTIFY THAT THIS AIRCRAFT ~~[illegible]~~E HAS BEEN INSPECTED IN ACCORDANCE WITH A 100 hr INSPECTION AND WAS DETERMINED TO BE AIRWORTHY. SIG [signature] DATE 11-27-72 TOTAL TIME 1766.2 M-1922477A 1785.82	

17

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

AIRCRAFT LOG

REMARKS	SIGNATURE
I CERTIFY THAT THIS AIRCRAFT ~~ENGINE HAS~~ BEEN INSPECTED IN ACCORDANCE WITH A 100 HR INSPECTION AND WAS DETERMINED TO BE AIRWORTHY. ~~SIG~~ [illegible] DATE 3-20-73 TOTAL TIME ~~1866.0~~ ~~M-19226780~~ 1885.0 I CERTIFY THAT THE ALTIMETER AND STATIC SYSTEM TESTS REQUIRED BY FAR 91.170 HAS BEEN PERFORMED. THE ALTIMETER HAS BEEN TESTED TO 20,000 FEET 11-5-75 [signature] A+P PILOT	

18

NOTICE:--Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

N C .....

Date Year Mo.	Day	Time in Air Hrs.	Min.	Passengers Carried	NATURE OF FLIGHT
					6-5-73
					REMOVED LEFT AUXILIARY FUEL CELL P/N 454-332 (CONDT. LEAKING).
					REMOVED RIGHT AUXILIARY FUEL CELL (CONDTN LEAKING). P/N 454-333.
					INSTALLED RECONDITIONED FUEL CELL LEFT AUXILIARY. P/N 454-332 S/N F-641
					INSTALLED RECONDITIONED FUEL CELL RIGHT AUXILIARY P/N 454-333 S/N 2599
				INSPECTED	L & R AUX. TANKS FOR LEAKS &
				OPERATION	- OK. [signature]
				6-5-73	M-1977477A
Total Forward					

Place of Last Airplane Overhaul .....

Date of Last Overhaul .....

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

AIRCRAFT LOG

REMARKS

I CERTIFY THAT THIS AIRCRAFT ~~ENGINE~~ HAS BEEN INSPECTED IN ACCORDANCE WITH A 100 HR INSPECTION AND WAS DETERMINED TO BE AIRWORTHY.

SIG. [signature] DATE 6-9-73

TOTAL TIME 1970.0

VOR CHECK 7-20-73
TT 1985.27

I CERTIFY THAT THIS ~~AIRCRAFT~~ AIRCRAFT ~~ENGINE~~ HAS BEEN INSPECTED IN ~~ACCORDANCE WITH~~ A 100.0 INSPECTION AND WAS DETERMINED TO BE AIRWORTHY.

SIG. [signature] DATE 8-24-73

TOTAL TIME 2070.0

14-1522477A

19

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

N C .....

Date Year Mo. Day	Time in Air Hrs. Min.	Passengers Carried	NATURE OF FLIGHT
10-12-73			ENGINE S/N L-3319-55A LEFT
REMOVED FOR			HIGH TIME. TOTAL TIME
SINCE NEW			2084 HRS.
10-12-73			ENGINE S/N L-3144-55A L.H.
INSTALLED AFTER			OVERHAUL. TOTAL TIME
SINCE NEW			1974 HRS.
			Andy Smith IA1537859
Total Forward			

Place of Last Airplane Overhaul .....

Date of Last Overhaul .....

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

AIRCRAFT LOG

REMARKS	SIGNATURE
10-12-73. INSPECTION CONDUCTED I/A/W MANUFACTURERS SERVICE MANUAL. ELECTRIC TRIM TAB MECHANISM REPAIRED. L.H. ENGINE STARTER SOLENOID REPLACED. VARIOUS ITEMS OF HARDWARE REPLACED ON BOTH MAIN LANDING GEAR. I CERTIFY THAT THIS AIRCRAFT WAS INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. TOTAL TIME SINCE NEW 2089.8 HRS. A&P. Death IA 1537859	
I CERTIFY THAT THIS AIRCRAFT ENGINE HAS BEEN INSPECTED IN ACCORDANCE WITH A 100 INSPECTION AND WAS DETERMINED TO BE AIRWORTHY. SIG. A&P PICHOS DATE 11-21-73	
TOTAL TIME 2089.0	

20

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

N C .....

Date Year Mo. Day	Time in Air Hrs.	Min.	Passengers Carried	NATURE OF FLIGHT
NOV-9-73				VOR STATION CHECK RECIEVERS #1 + #2 yearly VOR-170° RADIAL
				CHECK ONE AGAINST OTHER 3° BETWEEN #1 + #2 L ENGINE 2140 HRS
				Hauck 183C196CFDTS
NOV-16-73				VOR STATION CHECK RECIEVERS #1 + #2 ABE VOR 170° RADIAL
				ONE AGAINST OTHER 3° BETWEEN #1 + #2 L ENGINE 2169.7 HRS Hauck 183C196CFDM
NOV 20 73				VOR STATION CHECK RECIEVERS #1 + #2 ABE VOR 150° RADIAL
				ONE AGAINST OTHER 3° BETWEEN #1 + #2 L ENGINE 2187 HRS Hauck N5501C
Total Forward				

Place of Last Airplane Overhaul .....

Date of Last Overhaul .....

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

AIRCRAFT LOG

REMARKS	SIGNATURE
12-[illegible]-73 INSTALLED EMERGENCY BEACON CORP MODEL EBC 102A AT STATION 138 L.H. SIDE AFT CABIN COMPARTMENT. NEW EMPTY WT. 2431.5 LBS. EMPTY WT. C.G. 83.12 INS. MOMENT 202105. USEFUL LOAD 1168.5 LBS. SEE DWG & FAA FORM 337 IN ACFT. RECORDS Shelby S. Lark IA 1537859	
12-4-73 REMOVED AVCO-LYC [O-320-B1A # L-3329-55A DUE TO HIGH TIME INSTALLED AVCO-LYC [O-320-B1A # L-3319-55A TT 2084.0 "0" SINCE NEW. RUN IN & RETURNED TO SERVICE. 100.00 INSPECTION COMPLETED ON INSTALLATION R. NACELL (R TACH 21781) [signature] A+P IA 1537859	

21

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

N C .....

Date Year Mo.	Day	Time in Air Hrs.	Min.	Passengers Carried	NATURE OF FLIGHT
					May 10, 1974 - Replaced both
					repair to electric trim switch -
					rivets in the left nacelle - replaced
					repaired the left wheel well cover
					trim tab rod to horn - adjusted
					drain hoses - repaired the rt.
					engine sump drain fitting - replaced
					to the manifold - lubed & freed up th
					C/W P.S.L. 667 (Stabilator torque
					also stripped and repainted exh
					Torque Tube Bearing Blocks) Remove
					Rt. Tach - 2217.64 Lt. Tach. 2240.33
Total Forward					

Place of Last Airplane Overhaul .....

Date of Last Overhaul .....

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

AIRCRAFT LOG

REMARKS	SIGNATURE
inbd. fuel tank quantity transmitters - made temp. serviced air in both propellors - replaced missing tail nav lite bulb - resealed the rt. main strut - and replaced the rt. one - rebushed the stabilator elevator trim cable tension - replaced cockpit fuel engine alternate air control - rerivetted the rt. ed the rt. engine fuel line from the injector servo lt. throttle control - rebushed the cowl flap linkages. tube bolts) C/W P.S.L. 599 (Inner wing corrosion) aust track - both sides - C/W P.S.B 411A (Stabilator d & inspected both ailerons per AD 74-10-3 Don Ogden A&E 765904	

22

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

N C .....

Date Year Mo.	Date Day	Time in Air Hrs.	Time in Air Min.	Passengers Carried	NATURE OF FLIGHT
					10/2/64 Installed New Battery
Total Forward					

2. TOCH 2283.6 HRS.

SUMMIT AVIATION, INC.
SUMMIT AIR PARK
MIDDLETOWN, DELAWARE
F.A.A. APPROVED
REPAIR STATION 1216

Place of Last Airplane Overhaul .....

Date of Last Overhaul .....

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

REMARKS	SIGNATURE
Oct. 11, 1974 A Whelan HT, 1-3X and HR-14 stroke system and a Alcor Economix EA 36-4 EGT system were installed - See FAR 337 this date for details. - New empty wt. 2441.9 lbs. New E.W.C.G. is 83.2" aft of datum - new useful load is 115-8.1 lbs. Don Ogden 1A 765-904	23
Oct. 11, 1974 Installed Piper Kit # 760 783 (Aft bulkhd. to fin reinforcement) per AD 74-16-8, Installed Piper Kit #757 162 (Aileron Nose Bulkhead Replacement.) per AD 74-10-3 Tightened fwd seat back hinge nuts & saftied - Installed cabin door lock - replaced baggage door hold open rod - replaced missing rivnut in rt. wheel well - installed new bumper in rt. wheel well - repositioned lt. center aft seat track anchor nut. Drilled out rusty screws in fin cap and replaced - secured the defroster duct in the nose - Tightened lt. aileron control rod bolt	

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

N C .....

Date Year Mo.	Day	Time in Air Hrs.	Min.	Passengers Carried	NATURE OF FLIGHT
					Cont.
					replaced missing screws in the lt. wing-
					repaired wire and replaced bulb in dome
					light- Cleaned & painted battery box-
					unplugged drains - replaced lt. main
					gear door rod bolt - relined the
					both brake linings - installed new bolts
					in nose gear linkage - replaced nose
					tire & tube - replaced the lt. starter
					relay - I Certify That This Aircraft Has Been Inspected In Ac-
					Secured cordance With A Annual
					loose switches.
					Vacuumed Inspection And Was Determined To Be In Airworthy
					interior Condition. Hours In Service Lt. Tach: 2284.0
Total Forward		All ADs Ckd. thru 74-20			Oct. 11, 1974 Don Pyle

Place of Last Airplane Overhaul ..... Date .....

Date of Last Overhaul ..... IA 765904

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

AIRCRAFT LOG

REMARKS	SIGNATURE
12-26-74- Replaced trim switch bracket on control wheel - replaced rt landing lens - cleaned bulb connection ob rotating beacon - rebushed stabilator trim.	Don Ogden A&E 765404

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penal-

N C .....

Date Year Mo. Day	Time in Air Hrs.	Min.	Passengers Carried	NATURE OF FLIGHT
2/1/79				Installed DME-190, AT-50A, and Trav-Cal Digitizer.
				New aircraft empty weight : 2451.9 lbs
				New aircraft empty c.g. : 83.1"
				New aircraft empty moment : 203754.1" lbs
				New aircraft useful load : 1148.1 lbs
				Jacob Palbet A&E 1926363
Total Forward				

Place of Last Airplane Overhaul .....

Date of Last Overhaul .....

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

AIRCRAFT LOG

REMARKS	SIGNATURE
May 15, 1975 50 Hour Insp. repaired both main gear doors check. Replaced the ELT battery - Rt. Tach - 2343.7 Don Ogden	Clw - Lubed gear - and did retraction Lt. Tach 2367.6 - A&E 765 904
June 18 1975 Tach Reads 2371.97 Replaced Lt Main Gear Assy Strut Housing Type IV 20750 Gear Bungee, Reinstalled Lt Gear Also using New 'O' rings Torque link bolts & bushings Accomplished Gear retraction Test & Trim Ck OK	Charles Stoddart A&P 1959441

25

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

N C .....

Date Year ..... Mo.	Day	Time in Air Hrs.	Min.	Passengers Carried	NATURE OF FLIGHT
Total Forward					

I CERTIFY THAT THIS AIRCRAFT HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL ~~INSPECTION AND WAS DETERMINED TO BE IN~~ AIRWORTHY CONDITION. TIME IN SERVICE R/E 2385.65 HRS. 10-23-75 DATE.

Carl R Clendenin

~~CARL R. CLENDENIN A & P 1481102~~
INSPECTION AUTHORIZATION

Place of Last Airplane Overhaul .....

Date of Last Overhaul .....

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

AIRCRAFT LOG

REMARKS	SIGNATURE
10-23-75 - ANNUAL INSPECTION PER PIPER INSPECTION FORM - SERVICED BATTERY + BRAKE RESERVOIR - INSTALLED NEW L/H ALTERNATE AIR CONTROL - INSTALLED NEW ROTATING BEACON LAMP - INSTALLED NEW CABIN DOOR SEAL - REPAINTED BATTERY BOX - INSTALLED ALL NEW BRAKE LININGS + DISC - INSTALLED NEW VOLTAGE REGULATOR - AD 75-5-4 P/C/W (WHELEN STROBE LIGHTS) - AD 74-26-9 C/W (BENDIX MAGNETO DRIVE BUSHINGS) - AD 75-9-15 P/C/W (FUEL MANIFOLD GASKET C/W SB 464 (TAIL BLOCK RIVET INSP) - INSTALLED NEW L/H TACHOMETER READS 00.00 OLD READS 2409.57 R/H TACH 2385.65 Hours	Carl R Clendenin IA 1680102

26

NOTICE:--Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

N C .....

Date Year ..... Mo. Day	Time in Air Hrs.	Min.	Passengers Carried	NATURE OF FLIGHT
				I certify that the altimeter and static system tests required by FAR Part 91.170 have been performed. The altimeter was tested to 20,000 feet Date 17 Nov 1995 Static system test Date 20,000 Signature M. O. Zeltz Reading Aviation Service, Inc. Repair Station #1795
Total Forward				

Place of Last Airplane Overhaul .....

Date of Last Overhaul .....

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

AIRCRAFT LOG

REMARKS	SIGNATURE
12-12-75 - INSTALLED NEW FLAP SWITCH - 760 950 (PLACARDS) - R/E TACH READS Carl Clarke	INSTALLED PIPER KIT 2403.25 Hours A&P 1648102
12/29/75 Installed IC388 radio coupler and IC493 glideslope coupler. See 337 this date.	Reading Aviation Serv. C.R.S. # 1703 William Kahle
Empty Weight 2453.6 " C.G. 83.09	

27

NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

PERIODIC

PERIODIC INSPECTION REPORT

Aircraft

Mfg. .....

Model .....

License No. .....

Time to Date—Hrs..... Min.....

...de each 100 hours of flight and also immediately prior to presentation for inspection for renewal of certificate

Note condition and list repairs, replacements, etc.

Engine

Mfg. .....

Model .....

Serial No. .....

Total Time Hrs. ..... Min. .....

Fuselage, Tail Group and Covering		
Wings and Ailerons, Flaps and Covering		
Landing Gear & Tail Wheel or Skid and Tires		
Engine Installation and Cowling		
Fuel Tanks and Connections		
Control Cables & Pulleys Internal & External		
Struts, Fittings and Wires		
Alignment and Condition of Propeller	Hub Design Blade Design	Serial Serials
Instruments, Lights, Starter & Battery		

DATE .....Inspected by .....No. .....Address .....

Licensed Mechanic .....

NOTICE -Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.