

# SERVICE



# LETTER

Service Letter No. 424

April 20, 1964

TO: Distributors, Dealers, Certified Service Centers and Owners

SUBJECT: Installation of "Generators On" Placard

MODELS AFFECTED: PA-30 Twin Comanche, Serial Numbers 30-1 to 30-404 inclusive

In order to preclude the possibility of the generator switches being inadvertently left in the "off" position, a "Generators On" check has been added to the take-off check list placard on current production aircraft.

Since the subject aircraft, within the serial numbers listed above, were manufactured prior to the addition of "Generators On" to the take-off check list, a placard indicating "Generators On" is being made available.

The "Generators On" placard is to be placed at the bottom of the take-off check list and positioned as shown in the illustration on the reverse side of this letter.

There may be a few aircraft, within the serial numbers listed above, that have had the subject placard installed, in which case it will not be necessary to comply with this letter.

The subject placard shall be procured from your Piper distributor.

#### NOTE TO DISTRIBUTORS

The "Generators On" placard will be supplied in sufficient quantity on an automatic factory distribution basis. It will not be necessary to order these placards from the factory.

Very truly yours,


PIPER AIRCRAFT CORPORATION

A handwritten signature in dark ink, appearing to read "W. C. Holmes".  
W. C. Holmes  
Service Manager

WH:jf

**PIPER AIRCRAFT CORPORATION, LOCK HAVEN, PA., U. S. A.**

# INSTALLATION OF "GENERATORS ON" PLACARD



SERVICE LETTER

**~~424~~**