

INSTALLATION ■ OPERATION ■ SERVICE

Right Engine Prop

RIGHT HCE2YL-2BLS / J 2663-4

BG 523

LEFT ENGINE HCE2YL-2B5

Hartzell

**propeller owner's
manual
& log book**

**D.O.A. -
F.A.A.
APPROVED
MANUAL
115 F**

"Compact" Models HC-C2Y, HC-C3Y, HC-F2Y, HC-F3Y,
HC-E2Y, HC-E3Y, HC-G2Y, HC-G3Y, (P)HC-L3Y,
BHC-L2Y, HC-H3Y, (P)HC-J3Y, BHC-J2Y,
() HC-I2Y, and () HC-M2Y — Constant Speed and Feathering

HARTZELL PROPELLER, INC. - PIQUA, OHIO

PROPELLER MAINTENANCE RECORD

LEFT ENGINE

Hub Model _____

Blade Design _____

Diameter _____

Hub Ser. No. _____

Blade Ser. Nos. _____

No. 1 _____

No. 2 _____

No. 3 _____

PITCH RANGE

High _____ Low _____

Feather _____ Reverse _____

Governor Model _____

RIGHT ENGINE

Hub Model HCE24L-2BLS

Blade Design J 7663-4

Diameter 74"

Hub Ser. No. BC 523

Blade Ser. Nos. _____

No. 1 B72082

No. 2 B77351

No. 3 _____

PITCH RANGE

High _____ Low 12.0°

Feather 75.2° Reverse _____

Governor Model _____

DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS

[illegible]

C/R
L TURNING

VALLEY PROPELLER SERVICE INC.
SERVICEABLE PARTS TAG

CUSTOMER NELSON AIR SERVICE
W. O. NO. 10903 SER. NO. BG523
MODEL ACE214-2BS PART NO. 1
PART NAME PROPELLOR QUANTITY 1
REMARKS Propeller completely
overhauled, blades cold rolled
as per AD #77-12-06.
INSPECTOR Cliff Johnson DATE 2-10-86

DATE

1-6-76

3/12/86

3/12/86

RECEIVED 1000 R. NELSON HHT 172923

7-3-89 AKTINT 4521 Amended Both pages with Eng. H & Bill

PERTAINING TO AIRCRAFT
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
1-6-76	RETAD	1958.0 2200 right side W81734	Phil L. A.P. 1856340
3/12/86	2133	PROP COMPLETE OH SER YELLOW TAG.	K. L. Nelson A.P. 194123
3/12/86	2191	PROP COMPLETE OH SER YELLOW TAG	K. L. Nelson A.P. 194123
7-3-89	AKTAT 4521	Inspected Both pages with Eng. 1d + 1510	

SkyView Aviation

-END

Date: 02/20/2021

X

Make: Hartzell
Model: HC-E2YL-2BS
LP-S/N: BG523


Advantage Aviation
South Valley Regional Airport
7220 S. 4450 W.
W. Jordan, UT 84084
801-755-5398

W/O:
LH Tach: 702.8
TSPOH: 808.8

C/W 100HR/Annual inspection IAW Piper PA30 Maintenance Manual & Multi Engine Inspection Guide. Clean and dress prop. I certify that this **propeller** has been inspected in accordance with a **100 HR/Annual** inspection and determined airworthy this date

The aircraft, airframe, aircraft engine, propeller or appliance identified above was repaired and inspected in accordance with current Federal Aviation Regulations and is approved for return to service. Pertinent details of the repair(s) are on file at this Facility under the above referenced Work Order.

Date: September 15, 2022

Signature: 
Huy Bui 36883251A

[illegible]

HOME OF *Hartzell* PROPELLERS

This is an invitation to visit the home of Hartzell propellers in Piqua, Ohio. Here you'll see how design know-how . . . large and complete production facilities . . . high standards of workmanship . . . rigid inspection and testing procedures . . . assure unquestioned safe and superior performing propellers. Wherever you may be, you can look with confidence to our worldwide sales and service organization, backed by the progressive 98-year-old name: HARTZELL.



2601
266

181
266
8211

HARTZELL PROPELLER, INC. - PIQUA, OHIO