N8614 Y AIRCRAFT LOG



OWNER

NAME	ADDRESS
POWER AERO INC	321 PLAIN FIELD PILE
	SciTUATE, RI 02857 1050 S. Stole St.
2 Airsquire, Inc.	Dover, DE 19901
3	
	AND THE RESIDENCE OF THE PARTY
4	natural designation of the second
5	
6	

If this book is found, please return it to the owner.

AIRCRAFT DESCRIPTION

Registration No. N8614Y Popular Name: CoMANCHE 1968 Wodel: _ PA -30 Type Certificate No.: A I EA Serial No.: 30-1754 BLUE + BLACK ON WHITE colors: Propeller Manufacturer: HANTECLL Engine Manufacturer: LyCominG Original Propeller Model: HC EQYL-2BS (KFT) (LEFT) HCEZYL-2BLS (RIGHT) LIO-320 BIA (RIGHT) Hub or Serial Number: Single Serial Numbers: Single Left BG - 3659 Left 1- 3778 - 55 A Right BG - 3679 Right 1-3776-66C **Blade Numbers** Right Left B 78796 B 37901 B 75 779 B78928

=	Aircraft Time N8614Y rder	Moderan
-	Date 6-6-95 Total Time 1969.4 L/tach, 1971.3 R/tach, 4019.4 TAT W/O 14 05 23	
	I certify that this Frame has been inspected in accordance with annual inspection (using manufacturers	
	an approved insp. progedures) and was round to be in	
	listed in the back of the airframe log book.	
	For CRS #NCLR674G	
,	1. OPS checked gear warning system, system checked normal. 2. Right fuel pressure light inop-found left and right tank lights inop-repaired bulb holders. 3. Checked all cockpit lights, all check OK.	c gauge
	4. Complied with S/B 518C(Oil Bypass Valve) in accordance we service letter 1428, repaired units on left and right en	
	5. R&R ELT batteries IAW FAR 91.207, next due 6/97. 6. Complied with A/D 77-13-21(Burgees) Par B by R&R L&R bun	
Total Carry	NOREAST AVIATION SET New Bedford Regional Airs (508) 996-1832 FAX (508	oort 991-3266

N8644Y 6-6-95 M W/O 14 0.5 23

 Complied with A/D 79-12-08(Fuel Selector Valve) complied by inspection and S/L 851, no defects noted.

8. Complied with A/D 83-10-01(Fuel System) by inspection, no defects noted.

9. Complied with A/D 94-13-10(Stabilizer Inspection) by inspection.

10. Complied with A/D 93-02-05(Fuel Inj Lines) by inspection on left and right engines IAW S/B 342B no defects noted.

11. Complied with A/D 82-07-03(Janitrol Heaters) by pressure decay test and 100 hr inspection, OPS checked OK.

12. Sealed left main fuel cell sender unit.

13. Installed chafe material on right starter lead.

14. Sealed fuel sender terminals as needed.

15. R&R right air intake scat hose.

16. R&R fresh air inlet scat hose.

17. R&R left main tire assy. and tube assy.

18. Cleaned left and right exhaust tracks.

19. R&R left aux fuel panel gasket with customer supplied unit.

20. A/C was run up on ground, leak checked, OPS checked OK.

nte No.

	Aircraft Time		Recorder	N.
Date	This Date	Total	Reading	Maintenance
	Brought Forward		1	V8614Y
		6/6/95 W.O. 14	05 23	
		defi	coster so	distribution box to cat hose. Thure for
			NO	REAST AVIATION SERVICES New Bedford Regional Airport 9 996-1832 FAX (508) 991-3266 C. R. S. #NCLR674G
otal To Carry Forward			T)	

	6-6-95 N8641Y W/O 14 05-23P 4019.4 TAT A/C Log	-
and Remarks	1. R & R L/H Aux Fuel Cell with P/N 454-332 S/N M326 See Tag Attached- Leak CK OK	Certificate No.
	For Cl'S NCLR674G	
	The component identified was inspected in accordance with clation of the Federal Aviation Agaptroved for return to service. Pertinent details of the repair a this repair station under order. PIPER FUEL CELL Component LEFT HAND AUXILIMANUFACTURES. 201 4/5 A.T.S. 201 4/5 P/N 454-332 S/N M-326 Work Order No. F050495011 Date JUN 0 8 1995 Signed Anitenance Release For Maintenance Rele	SERVICEA! D.O.T./F.A.A. Approved Repair Station AIRCRAFT FUEL CELL 300 Airport Rd. Eagle River, WI 54

Irt No., Ser. No.

UXILIARY

riation Agency, and is ce with current reguied was repaired and

repair are on file at

pair Station No. NL5R071N

CELL REPAIR

WI 54521

ed Repair Station

for

lease Form

	Aircraf	t Time	Recorder	Maintenance
Date	This Date	Total	Reading	11
9-7-95	Brought Forward	4045	1997	INSTAILED STC# SASTOCH
				TRAILING EDGE INBOARD
				WHITE All WORK WAS DON
				manual SES FORM 33
7				BALANCE - END -
1				
N. S.				
K				
1				
Total To Carry Forward				

Registration	No.	
	THE RESERVE THE	

and Remarks	Signature	Certificate No.
for KNOTS 2U INC. WING FILLET. OR		
CLAPS, PAINTED USING EMPON# N8017U		
ACCERDANCE WITH KNOTS 24 WSTALLATE	w	
THIS DATE. NO CHANGE IN WEIGHT &	~	
	SROMANO	28381951 AS

	Aircr	aft Time	Recorder	
Date	This Date	Total	Reading	Maintenanc
	Brought +			
	model instruction in the instruction instruction in the ins	ected and found 2258 by,	to comply with FAR 91.413 NICS, INC Hyannis, MA	
	Mod	el 10/627-0/3	Apposovic Corporation of 20,0	s been
al To	and r Insp. for, C	neets the requ	ONICS, INC. Hyannis,	

CARD TEST ALTIMETER

	0
5	339
19/9	0/62
9	#
Date	Part
we	222
tress	CEC
No.A	No.(
Model 1	Serial
Mod	Se

ERROR SCALE

Tolerance (± Feet)	100 1100 1120 1130 1200 1200 1200 1200 1	
	3888	
Altritude (Jeet)	14,000 16,000 18,000 20,000 22,000 25,000 35,000 40,000	
Tolerance (± Feet)	6,8,9,3,2,5,5,5,6,6,8,6,6,6,6,6,6,6,6,6,6,6,6,6,6	
	300000000000000000000000000000000000000	
AltritriA (JeeF)	-1,000 1,000 2,000 3,000 4,000 8,000 10,000	

erance Tol Test: Test Leak First Hysteresis Case

75 Feet Max. Altitude) Max. Altitude Point Point Test Test Test Effect Jo (40% of Second (50%

After

GRIFFIN AVIONICS,

GN1R17 Hyannis, Mass Repair Station Y

H

and Remarks APIT-HOLD.	Signature Certificate N
13-21 paragraphs a & b. Paragraph both bungee arms due to cracks. In trant inspection per AD 95-20-07. justed as needed. Checked RH flap both aux fuel caps and installed a chafing on aileron and flap. Installed change in weight & balance).	TIME: 2011.17. Replaced bungee cords. Complied with AD 77- a due at 3011.17. Bungees due at 2511.17 or 05-98. Replaced espected main gear side brace studs by flourescent dye pene- Replaced baggage door seal. Replaced cabin door seal & ad- p extensions, found ok. Sealed windshield at top. Replaced all new fuel door gaskets. Adjusted gap seals to prevent talled K2U baggage door strut (see 337 this date, negligible Robert W. Lind IA 543669529. (WEBCD AIRCRAFT CD.)
Signed Robert Lind	The state of the s

accordance and was dete released for	Installed n D's 79-12-08 Dilizer insp	Patrick Modern Patrick Modern No. 1856340 IA 1856340 Is and discontracted value of the fuel selection 93-0	been insperion as per the condition of t	s. Replaced lter and cent assy.CW the	tral	intenance
Total To Carry Forward						

and Remark	N8614Y 9-23-96 Tach. 0000.3 AFTT 4123.0 Removed both engines due for overhaul and installed two factory overhauled engines.S/N L-1161-55A left side and S/N L-311-66A right side. Installed new lord mounts both sides and all new fuel and oil hoses. Installed new oil coolers both sides.Replaced left cylinder temp bulb and indicator. Installed new right Aux fuel tank with all new gaskets.Reinstalled original props. Patrick Murphy Asso 1856340	icate No.
9-23 C/W AD C/W AD	196 AFTI-4123.0 Cfur AD 79-12-8 leg vised AD B3101 fuel revery by clind Detle APIBO 346 94-13-10 By Duyetin Loil Koryce	

	Aircraft Time		Recorder	M	aintenance
Date	This Date	Total	Reading		- mendici
	INSTA- KITS: AND W AIRCR UPDAT	SPEED SP OW COWL. AFT WEIGH	ATS, SPERSEE 337 TED AND FI	D SPLITTERS, THIS DATE LIGHT MANUAL	
Total To Carry Forward					

N 86147			
I Certify that A' Required by FA	R 91 413 Have	Been Pe	erformed.
S/N 337	261	Date	9-18-97
S/N N/	-	Date	
Work Order #	00182		N 86/4 Y
Phoenix Air, Ca Repair Station	rtersville, GA	247	I Certify that Altimeter and Static System Tests Required by FAR 91.411 Have Been Performed. Aerosowic Static System Date 9-18-97
Repair Station	ESPROSID		Altimeters Tested to 20,000 ft LH S/N C 100 20 2 Date 9-18-97
			LH S/N C 100202 Date 9-18-97 RH S/N Date Date Work Order # 00182
			Signed # 147 2478424
Total To Carry Forward			Phoenix Air, Cartersville, GA Repair Station ESPR691D
			Tropan Station Est Royts

and Remarks		Signature	Certificate No.
9-23-47 KETALL-14733	2 co. 2	e conferm	Or Pracing
AFTI- 42700	Des bee	engthein	occobone
Refus Ett 12 attue		- www. Deng	
Dec - 6/19 C/w AA		Remil Bo	
17-13-21 Para C	Ceiever	Tay conde to	
4/4 40 79 12-08 My			0-
Yw 40-33-10-01 for	estar contra	strong GWAD 94	1-13-10 By lugt
Burge Corle Jor Do	heel imption	one Nolling	Janes.
Dugee Gorle for bo	the green	WED JUST	182540
Referred and their Lewis	2 .		

and Rem	Strip A/C with El Dorado Pr 4042 chemical,	ature	Certificate No
	inspect aircraft skin for corrosion & imperfections.	A STATE	
	Sand & repair all fiberglass, and fill minor surface	. Militar	
	dents with lightwieght filler. Etched aircraft with		
	El Dorado AC-5 aluminum brightner & alodined		
	with Doradokote #7. Primed aircraft with 724-400		
	epoxy chromate. Painted overall with 570-563 Jet-Glo.		
	Trim colors; 527-690 Aristo Blue Jet-Glo		
	577-629 Desert Sand Jet-Glo		
	Aircraft Refinishers N 8614 Y		
	2333 Delray Rd.		
	Thomaston, Ga. 30286 1/7/98		
	BEAUTHORISE TO THE SECOND SECO		
			RI SPALE RESERVED

	Registration No.	
N8614Y	Interior Work Order 1131122	4-06-98
1. 2. 3. 4. 5. 6.	Customize new seats with Skandia (flame resistant) foam. Seat covers leather from Aeristo (color and name: Pelican AN-F-011 Aeronappa) Removed and repaired side wall bottoms and covered with Aeristo leat Pelican AN-F-011 Aeronappa and also Garrett leather, Color: Royal 8 Floor carpet customized using cut pile carpet from Douglass Interior P 828 Shell AZ3517. Fabricated two (2) aft bulkhead panels and covered with two (2) leather Rebuilt four (4) covered headrests with leather. Built backrest plate and covered with leather.	ther, color: 35 Berkshire, roducts, color:
Tom Mai Hill Airc	raft Interiors provided the customer of N8614Y all certificates of complete installed by Hill Aircraft Interiors 4-06-98. Thews raft & Leasing ation: ESER686D	iance for FAR 25.853 A & B fire burn tests from
5-6-98 A	TALL 204.65 C/W AD 79-12-8 FT-4327.65	Part 3 by Dyelian Pall At Pass 310

	Aircraft Time		Recorder	Maint
Date	This Date	Total	Reading	Maintenance
	Brought +		C/w A	0 74-128 By Dongeton De
10898	AFT - 4364	1.7	qw A	0 79-20-10 By Thy Rom 1
LE-	TACK-241. 7	7	E/co A	D 931001 ly Duyton
			C/w B	0941310 by Duption
10-98:	23-01 0/A	vol en	2000 B	ette lengenes, AD 98-21
	THE RESIDENCE OF STREET, SALES OF STREET			replaced Referred
				Lowling light. A
			A CONTRACTOR OF A CONTRACTOR O	seen reingerth ein
	_			de les en centros
137	The free free			
Total To Carry Forward				

Registration	No.	10.7等在是自治区。	
g		MICHAEL COM CONTROL SERVICE CONTROL OF STREET	

and Remarks		Signature	Certificate No.
gui 50HOS- Che	AD 77-13-21 RI Per	B Inspection C	0
perio 100+05	Replaced Berges.	Vijval Due 10.	490248644
again 50HRS	deplacement Due		
	W AD 9804-07 Int	VI ~	A STATE OF THE PARTY OF THE PAR
U/A noticet alogo ?			
tip stude power su Indea Replaced			
cecondame andle	a Aunual si	exection At per	Peper Joran
consteon.			10
- Well	TA (85/340 -		
- 0)		

	Aircraft Time		Recorder	Mala	
Date	This Date	Total	Reading	Maintenance	
	Brought Forward				
2-1-99	Dew Con	rod to	de Ju	o Dolos	
A	Dew Conf				
TA	ce -		2	0	
	13	7. 6	DA	X (1891386	
	1		1 22 . 6		
(Sec. 1919)		344	0.0		
18 3 8		1000	2 3		
Total To			NAME OF THE PARTY	A STATE OF THE STA	
Carry Forward					

N8614Y 03-04-04 AIRFRAME LH TACH 861.82 TT 4984.82 REPLACED ELT (BATTERY EXP. DATE 03/06) OP CHECK ELT PER FAR 91.207 SERVICED BATTERY. STATIC SYSTEM EXP. DATE 03-05 CLEANED FUEL SCREEN & FUEL PUMP FILTERS INSPECTED FUEL VENTS AND CAPS. LUBED FLIGHT CONTROLS. LUBED TRIM DRUM & FLAP TRACKS. CHECKED BRAKES, INSPECTED WHEELS AND TIRES, GREASED GEAR, PERFORMED EMERGENCY GEAR EXTENSION CHECK. CHECKED VACUUM REGULATOR FILTER. INSPECTED ENGINE CONTROLS. PERFORMED ELECTRICAL CHECK. FLUSHED & SERVICED BRAKE SYSTEM. INSTALLED MISSING RIVET IN RH AUGMENTOR. REPLACED 2 EACH CABIN HEATER SCAT TUBING. REBUILT RH & LH BRAKE CALIPERS. CLEAN DEBRIS FROM RH MAIN FUEL TANK, INSTALLED COVER & REPLACED GASKETS & SEALS. REPLACED LH & RH BRAKE HOSES. REPAIRED FLAP INDICATOR SENDER. INSTALLED NEW PLACARD ON FUEL SELECTOR DISH. REPAIRED RH ENGINE AIR FILTER BOX. OVERHAULED BOTH FUEL SELECTOR VALVES. INSTALLED CORRECT BOLT IN RUDDER TRIM BUNGEE. ADJUSTED STAB TRIM DRUM END PLAY. REPLACED SERVO INLET HOSE ON RH ENGINE. REPLACED RH & LH AFT AILERON ROD ENDS. REPAIRED SWITCH WIRES ON RH & LH MAIN GEAR. REMOVED RATS NEST FROM CABIN UNDER FLOOR INSTALLED NEW INSULATION. REPLACED LH OUTBOARD TRIM TAB HINGE. REPLACED DOOR. REPLACED LH & RH FLAP RETURN SPRINGS. REPLACED LH ALTERNATOR BLAST TUBE SCAT HOSE REMOVED GEAR TRANSMISSION, OVERHAULED & REINSTALLED (SEE YELLOW TAG DATED 03/03/04). RIGGED LANDING GEAR. COMPLIED WITH THE FOLLOWING ADS: 77-13-21 BY REPLACEMENT & INSPECTION, 79-12-08 BY INSPECTION, 83-10-01 BY INSPECTION, 97-01-01R1 BY INSPECTION, 99-14-01 BY INSPECTION, 2001-17-13 BY INSPECTION & DATE MARK, 70-22-02 BY INSPECTION & MARKING (BOTH VALVES).	
ROBERT A. WEBER I CERTIFY THAT THIS AIRFRAME HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND HAS BEEN DETERMINED TO BE IN AN AIRWORTHY CONDITION. MANUEL S. WEBER AP515661251IA	,

