

## Aircraft Details

Use the query results with caution

Over time registration numbers are assigned to different aircraft and diverse data stores with inconsistent data are being joined

[Back to Query Entry](#)

## N Number: 8614Y

Last Action Date	2023-01-22		
Airworthiness Date	1968-11-18	Expiration Date	2027-05-31
Manufacturer_Name	PIPER	Model Name	PA-30
Registrant Name	AIRSQUIRE LLC	Street	9 E LOOCKERMAN ST STE 311
Registrant City	DOVER	Registrant State	DE
Registrant Zip Code	199018305	Country	UNITED STATES
Region	Eastern	Registrant Type	LLC
Fract Owner		Certificate Issue Date	2001-05-23
Status	N-Number Assigned and Registered		
Serial Number	30-1754	Aircraft Type	Fixed wing multi engine
Mode S Code	52752611	Year Mfr	1968
Aircraft Category	Land	Builder Certification	Type Certificated
Number Engines	2	Number Seats	6
Aircraft Weight	CLASS 1	Aircraft Cruising Speed	139
Airworthiness Classification	Standard	Approved Operation Codes	Normal
Engine Manufacturer	LYCOMING		
Engine Model Name	IO-320 SERIES	Engine Type	Reciprocating
Engine Horsepower/Thrust	0	Fuel Consumed	0.00

## ----- History 1 -----

Last Action Date	2020-10-02		
Registrant Name	AIRSQUIRE LLC	Street	9 E LOOCKERMAN ST STE 311

<b>Registrant City</b>	DOVER	<b>Registrant State</b>	DE
<b>Registrant Zip Code</b>	199018305	<b>Country</b>	UNITED STATES
<b>Region</b>	Eastern	<b>Registrant Type</b>	LLC
<b>Fract Owner</b>		<b>Certificate Issue Date</b>	2001-05-23
<b>Status</b>	First Notice for Registration Renewal		
----- <b>History 2</b> -----			
<b>Last Action Date</b>	2020-01-09		
<b>Registrant Name</b>	AIRSQUIRE LLC	<b>Street</b>	9 E LOOCKERMAN ST STE 311
<b>Registrant City</b>	DOVER	<b>Registrant State</b>	DE
<b>Registrant Zip Code</b>	199018305	<b>Country</b>	UNITED STATES
<b>Region</b>	Eastern	<b>Registrant Type</b>	LLC
<b>Fract Owner</b>		<b>Certificate Issue Date</b>	2001-05-23
<b>Status</b>	N-Number Assigned and Registered		
----- <b>History 3</b> -----			
<b>Last Action Date</b>	2017-09-15		
<b>Registrant Name</b>	AIRSQUIRE LLC	<b>Street</b>	9 E LOOCKERMAN ST STE 311
<b>Registrant City</b>	DOVER	<b>Registrant State</b>	DE
<b>Registrant Zip Code</b>	199018305	<b>Country</b>	UNITED STATES
<b>Region</b>	Eastern	<b>Registrant Type</b>	LLC
<b>Fract Owner</b>		<b>Certificate Issue Date</b>	2001-05-23
<b>Status</b>	First Notice for Registration Renewal		
----- <b>History 4</b> -----			
<b>Last Action Date</b>	2017-01-31		
<b>Registrant Name</b>	AIRSQUIRE LLC	<b>Street</b>	1679 S DUPONT HWY STE 100
<b>Registrant City</b>	DOVER	<b>Registrant State</b>	DE
<b>Registrant Zip Code</b>	199015164	<b>Country</b>	UNITED STATES
<b>Region</b>	Eastern	<b>Registrant Type</b>	Corporation
<b>Fract Owner</b>		<b>Certificate Issue Date</b>	2001-05-23
<b>Status</b>	N-Number Assigned and Registered		

----- History 5 -----

<b>Last Action Date</b>	2014-04-10		
<b>Registrant Name</b>	AIRSQUIRE LLC	<b>Street</b>	1679 S DUPONT HWY STE 100
<b>Registrant City</b>	DOVER	<b>Registrant State</b>	DE
<b>Registrant Zip Code</b>	199015164	<b>Country</b>	UNITED STATES
<b>Region</b>	Eastern	<b>Registrant Type</b>	Corporation
<b>Fract Owner</b>		<b>Certificate Issue Date</b>	2001-05-23
<b>Status</b>	First Notice for Registration Renewal		

----- History 6 -----

<b>Last Action Date</b>	2011-05-12		
<b>Registrant Name</b>	AIRSQUIRE LLC	<b>Street</b>	32 W LOOCKERMAN ST APT 201
<b>Registrant City</b>	DOVER	<b>Registrant State</b>	DE
<b>Registrant Zip Code</b>	199047313	<b>Country</b>	UNITED STATES
<b>Region</b>	Eastern	<b>Registrant Type</b>	Corporation
<b>Fract Owner</b>		<b>Certificate Issue Date</b>	2001-05-23
<b>Status</b>	Second Notice for Registration Renewal		

----- History 7 -----

<b>Last Action Date</b>	2009-10-08		
<b>Registrant Name</b>	AIRSQUIRE LLC	<b>Street</b>	32 W LOOCKERMAN ST APT 201
<b>Registrant City</b>	DOVER	<b>Registrant State</b>	DE
<b>Registrant Zip Code</b>	19904-7313	<b>Country</b>	UNITED STATES
<b>Region</b>	Eastern	<b>Registrant Type</b>	Corporation
<b>Fract Owner</b>		<b>Certificate Issue Date</b>	2001-05-23
<b>Status</b>	First Notice for Re- Registration/Renewal		

----- History 8 -----

<b>Last Action Date</b>	2008-09-16		
<b>Registrant Name</b>	AIRSQUIRE LLC	<b>Street</b>	2711 CENTERVILLE RD STE 400

<b>Registrant City</b>	WILMINGTON	<b>Registrant State</b>	DE
<b>Registrant Zip Code</b>	19808-1645	<b>Country</b>	UNITED STATES
<b>Region</b>	Eastern	<b>Registrant Type</b>	Corporation
<b>Fract Owner</b>		<b>Certificate Issue Date</b>	2001-05-23
<b>Status</b>	N-Number Assigned and Registered		

----- **History 9** -----

<b>Last Action Date</b>	2007-09-10		
<b>Registrant Name</b>	AIRSQUIRE LLC	<b>Street</b>	30 OLD RUDNICK LN
<b>Registrant City</b>	DOVER	<b>Registrant State</b>	DE
<b>Registrant Zip Code</b>	19901-4912	<b>Country</b>	UNITED STATES
<b>Region</b>	Eastern	<b>Registrant Type</b>	Corporation
<b>Fract Owner</b>		<b>Certificate Issue Date</b>	2001-05-23
<b>Status</b>	A second attempt has been made at mailing a Triennial Aircraft Registration form with no response		

----- **History 10** -----

<b>Last Action Date</b>	2007-06-07		
<b>Registrant Name</b>	AIRSQUIRE LLC	<b>Street</b>	30 OLD RUDNICK LN
<b>Registrant City</b>	DOVER	<b>Registrant State</b>	DE
<b>Registrant Zip Code</b>	19901-4912	<b>Country</b>	UNITED STATES
<b>Region</b>	Eastern	<b>Registrant Type</b>	Corporation
<b>Fract Owner</b>		<b>Certificate Issue Date</b>	2001-05-23
<b>Status</b>	Second Triennial Aircraft Registration Form has been mailed and has not been returned		

----- **History 11** -----

<b>Last Action Date</b>	2004-05-18		
<b>Registrant Name</b>	AIRSQUIRE LLC	<b>Street</b>	30 OLD RUDNICK LN
<b>Registrant City</b>	DOVER	<b>Registrant State</b>	DE
<b>Registrant Zip Code</b>	19901-4912	<b>Country</b>	UNITED STATES
<b>Region</b>	Eastern	<b>Registrant Type</b>	Corporation
<b>Fract Owner</b>		<b>Certificate Issue Date</b>	2001-05-23
<b>Status</b>	The Triennial Aircraft Registration form was mailed and has not been		

returned by the Post Office

----- History 12 -----

<b>Last Action Date</b>	2001-05-24		
<b>Registrant Name</b>	AIRSQUIRE LLC	<b>Street</b>	30 OLD RUDNICK LN
<b>Registrant City</b>	DOVER	<b>Registrant State</b>	DE
<b>Registrant Zip Code</b>	19901-4912	<b>Country</b>	UNITED STATES
<b>Region</b>	Eastern	<b>Registrant Type</b>	Corporation
<b>Fract Owner</b>		<b>Certificate Issue Date</b>	2001-05-23
<b>Status</b>	N-Number assigned		

----- History 13 -----

<b>Last Action Date</b>	2000-02-16		
<b>Registrant Name</b>	AIRSQUIRE INC	<b>Street</b>	30 OLD RUDNICK LN
<b>Registrant City</b>	DOVER	<b>Registrant State</b>	DE
<b>Registrant Zip Code</b>	19901-4912	<b>Country</b>	UNITED STATES
<b>Region</b>	Eastern	<b>Registrant Type</b>	Corporation
<b>Fract Owner</b>		<b>Certificate Issue Date</b>	1996-10-02
<b>Status</b>	The Triennial Aircraft Registration form was mailed and has not been returned by the Post Office		

\*\*\*\*\* No Deregistered Data Found \*\*\*\*\*

\*\*\*\*\* No Reserved Data Found \*\*\*\*\*

\*\*\*\*\* No FAA Accidents/Incidents Found \*\*\*\*\*

\*\*\*\*\* No NTBS Accidents Found \*\*\*\*\*

\*\*\*\*\* No NTBS Pre 1982 Accidents Found \*\*\*\*\*

----- SDR 1 -----

<b>Date Of Report</b>	1978-06-21	<b>Operator Control Number</b>	Z197817200092
<b>Date Of Occurrence</b>		<b>Aircraft Registration</b>	8614Y
<b>Aircraft Manufacturer</b>	PIPER	<b>Aircraft Group Code</b>	PA30
<b>Aircraft Manufacturer Model</b>	PA30	<b>Aircraft Make Model Sequence</b>	7103002

<b>Air Carrier Name</b>	Unknown	<b>Air Carrier Operation Code</b>	
<b>Operation Type</b>		<b>Stage Of Operation</b>	INSP/MAINT
<b>Severity Factor</b>	OVER 24 MO	<b>Air Transport Association Code</b>	Reciprocating Engine Cylinder Section
<b>Precautionary Procedures</b>	NONE	<b>Nature Of Condition</b>	OTHER
<b>Segment</b>	ENGINE	<b>Descriptive Name Of Part</b>	CYL
<b>Defective Location On Aircraft</b>	NO 2	<b>Failed Part Condition</b>	CRACKED
<b>Part Total Time</b>	0	<b>Part Total Time Since Overhaul</b>	0
<b>Component Manufacturer</b>		<b>Component Manufacturer Model</b>	
<b>Component Manufacturer Number</b>		<b>Manufacturer Part Number</b>	74468
<b>Ata Code</b>			
<b>Remarks</b>	CRKS IN FIN AREA OF BOTTOM SPARK PLUG HOLE NEAR EXH PORT		

----- SDR 2 -----

<b>Date Of Report</b>	1978-06-21	<b>Operator Control Number</b>	Z197817200091
<b>Date Of Occurrence</b>		<b>Aircraft Registration</b>	8614Y
<b>Aircraft Manufacturer</b>	PIPER	<b>Aircraft Group Code</b>	PA30
<b>Aircraft Manufacturer Model</b>	PA30	<b>Aircraft Make Model Sequence</b>	7103002
<b>Air Carrier Name</b>	Unknown	<b>Air Carrier Operation Code</b>	
<b>Operation Type</b>		<b>Stage Of Operation</b>	INSP/MAINT
<b>Severity Factor</b>	OVER 24 MO	<b>Air Transport Association Code</b>	Reciprocating Engine Cylinder Section
<b>Precautionary Procedures</b>	NONE	<b>Nature Of Condition</b>	OTHER
<b>Segment</b>	ENGINE	<b>Descriptive Name Of Part</b>	CYL
<b>Defective Location On Aircraft</b>	NO 4	<b>Failed Part Condition</b>	CRACKS
<b>Part Total Time</b>	0	<b>Part Total Time Since Overhaul</b>	0
<b>Component Manufacturer</b>		<b>Component Manufacturer Model</b>	
<b>Component Manufacturer Number</b>		<b>Manufacturer Part Number</b>	74468
<b>Ata Code</b>			
<b>Remarks</b>	CRKS IN FIN AREA OF BOTTOM SPARK PLUG HOLE NEAR EXH PORT		

----- SDR 3 -----

<b>Date Of Report</b>	1978-06-21	<b>Operator Control Number</b>	Z197817200090
<b>Date Of Occurrence</b>		<b>Aircraft Registration</b>	8614Y
<b>Aircraft Manufacturer</b>	PIPER	<b>Aircraft Group Code</b>	PA30

<b>Aircraft Manufacturer Model</b>	PA30	<b>Aircraft Make Model Sequence</b>	7103002
<b>Air Carrier Name</b>	Unknown	<b>Air Carrier Operation Code</b>	
<b>Operation Type</b>		<b>Stage Of Operation</b>	INSP/MAINT
<b>Severity Factor</b>	OVER 24 MO	<b>Air Transport Association Code</b>	Reciprocating Engine Cylinder Section
<b>Precautionary Procedures</b>	NONE	<b>Nature Of Condition</b>	OTHER
<b>Segment</b>	ENGINE	<b>Descriptive Name Of Part</b>	CYL
<b>Defective Location On Aircraft</b>	NO 1 CYL	<b>Failed Part Condition</b>	CRACKS
<b>Part Total Time</b>	0	<b>Part Total Time Since Overhaul</b>	0
<b>Component Manufacturer</b>		<b>Component Manufacturer Model</b>	
<b>Component Manufacturer Number</b>		<b>Manufacturer Part Number</b>	74468
<b>Ata Code</b>			
<b>Remarks</b>	CRKS IN FIN AREA OF BOTTOM SPARK PLUG HOLE NEAR EXH PORT		

## Aircraft Report

Insert Tail Number  
(do not include the "N" prefix):

8614Y

Go

- ☒ - Aircraft Registration
- ☒ - SDR Information
- ☒ - NTSB Information
- ☒ - FAA Information
- ☒ - FAA's Document Index files

### Database Update Cycle

Aircraft Registration: Last 09/01/2021 (weekly cycle)

NTSB Data: Last 09/01/2021 (weekly cycle)

SDR: Last 09/01/2021 (weekly cycle)

FAA Accident: 09/01/2021 (weekly cycle)

### Aircraft Information

**Owner Type:**

**City:** DOVER

**Zip:** 199018305

**Fractional Owner:**

**Aircraft Type:** Fixed wing multi engine

**Airworthiness Class:** Standard

**Serial Number:** 30-1754

**Last Action:** 2020-10-02

**Status:** 8614Y

**Aircraft Mfg:** PIPER

**Category:** Land

**Engines:** 2

**Weight:** CLASS 1

**Engine Mfg.:** LYCOMING

**Fuel Consumed:** 0.00

**Owner Name:** AIRSQUIRE LLC

**State:** DE

**Country:** US

**Model Year:** 1968

**Transponder Code:** 52752611

**Aircraft Model:** 7103002

**Cert Issue:** 2001-05-23

**Aircraft Model:** PA-30

**Amateur:** No

**Seats:** 6

**Cruising Speed:** 139

**Engine Model:** IO-320 SERIES

**Horsepower/Thrust:** 150

### Service Difficulty Report (SDR) Information

No Service Difficulty Reports Found

### NTSB Accident Information

No NTSB Accident Reports Found

### FAA Accident/Incident Information

No FAA Accident/Incident Reports Found

### FAA's Document Index files

Nothing listed in the FAA Document Index

MyAirplane.com - End of report for: 8614Y

The FAA & NTSB associates damage history by the tail number, not to the actual aircraft its currently assigned to.