

AviationDB

Aircraft Details

Use the query results with caution

Over time registration numbers are assigned to different aircraft and diverse data stores with inconsistent data are being joined

[Back to Summary](#)[Next Page](#)[Prior Page](#)

N Number: 700Y

Last Action Date	2023-10-19		
Airworthiness Date	1977-03-15	Expiration Date	2030-08-31
Manufacturer_Name	PIPER	Model Name	PA-23-250
Registrant Name	JA AERO LLC	Street	451 N CLAREMONT
Registrant City	CHICAGO	Registrant State	IL
Registrant Zip Code	60612	Country	UNITED STATES
Region	Great Lakes	Registrant Type	LLC
Fract Owner		Certificate Issue Date	2023-08-24
Status	N-Number Assigned and Registered		
Serial Number	27-7754076	Aircraft Type	Fixed wing multi engine
Mode S Code	52253264	Year Mfr	
Aircraft Category	Land	Builder Certification	Type Certificated
Number Engines	2	Number Seats	6
Aircraft Weight	CLASS 1	Aircraft Cruising Speed	150
Airworthiness Classification	Standard	Approved Operation Codes	Normal
Engine Manufacturer			
Engine Model Name		Engine Type	Reciprocating
Engine Horsepower/Thrust		Fuel Consumed	

----- History 1 -----

Last Action Date	2023-08-28		
Registrant Name	JA AERO LLC	Street	451 N CLAREMONT
Registrant City	CHICAGO	Registrant State	IL

Registrant Zip Code	60612	Country	UNITED STATES
Region	Great Lakes	Registrant Type	LLC
Fract Owner		Certificate Issue Date	2023-08-24
Status	N-Number Assigned and Registered		

----- History 2 -----

Last Action Date	2023-08-24		
Registrant Name	JA AERO LLC	Street	451 N CLAREMONT
Registrant City	CHICAGO	Registrant State	IL
Registrant Zip Code	60612	Country	UNITED STATES
Region	Great Lakes	Registrant Type	LLC
Fract Owner		Certificate Issue Date	2023-08-24
Status	Valid Registration from a Trainee		

----- History 3 -----

Last Action Date	2023-04-28		
Registrant Name	RAASCH DANIEL W	Street	824 W 3RD ST
Registrant City	GILMAN	Registrant State	IL
Registrant Zip Code	609381056	Country	UNITED STATES
Region	Great Lakes	Registrant Type	Individual
Fract Owner		Certificate Issue Date	2021-03-22
Status	N-Number Assigned and Registered		

----- History 4 -----

Last Action Date	2021-03-22		
Registrant Name	RAASCH DANIEL W	Street	824 W 3RD ST
Registrant City	GILMAN	Registrant State	IL
Registrant Zip Code	609381056	Country	UNITED STATES
Region	Great Lakes	Registrant Type	Individual
Fract Owner		Certificate Issue Date	2021-03-22
Status	N-Number Assigned and Registered		

----- History 5 -----

Last Action Date	2020-06-13		
Registrant Name	FARQUHAR AVIATION LLC	Street	1485 CENTRAL DR
Registrant City	SOUTHERN	Registrant State	NC

	PINES		
Registrant Zip Code	283872105	Country	UNITED STATES
Region	Eastern	Registrant Type	LLC
Fract Owner		Certificate Issue Date	2011-07-07
Status	N-Number Assigned and Registered		

----- History 6 -----

Last Action Date	2017-06-08		
Registrant Name	FARQUHAR AVIATION LLC	Street	1485 CENTRAL DR
Registrant City	SOUTHERN PINES	Registrant State	NC
Registrant Zip Code	283872105	Country	UNITED STATES
Region	Eastern	Registrant Type	LLC
Fract Owner		Certificate Issue Date	2011-07-07
Status	Second Notice for Registration Renewal		

----- History 7 -----

Last Action Date	2014-02-10		
Registrant Name	FARQUHAR AVIATION LLC	Street	1485 CENTRAL DR
Registrant City	SOUTHERN PINES	Registrant State	NC
Registrant Zip Code	283872105	Country	UNITED STATES
Region	Eastern	Registrant Type	Corporation
Fract Owner		Certificate Issue Date	2011-07-07
Status	Second Notice for Registration Renewal		

----- History 8 -----

Last Action Date	2011-07-07		
Registrant Name	FARQUHAR AVIATION LLC	Street	1485 CENTRAL DR
Registrant City	SOUTHERN PINES	Registrant State	NC
Registrant Zip Code	283872105	Country	UNITED STATES
Region	Eastern	Registrant Type	Corporation
Fract Owner		Certificate Issue Date	2011-07-07
Status	First Notice for Registration Renewal		

----- History 9 -----

Last Action Date	2010-05-18		
Registrant Name	PIEDMONT PARTNERS	Street	5809 KINGSWAY LN
Registrant City	KERNERSVILLE	Registrant State	NC
Registrant Zip Code	27284-9799	Country	UNITED STATES
Region	Eastern	Registrant Type	Partnership
Fract Owner		Certificate Issue Date	2004-05-13
Status	First Notice for Re- Registration/Renewal		

----- History 10 -----

Last Action Date	2007-05-15		
Registrant Name	PIEDMONT PARTNERS	Street	5809 KINGSWAY LN
Registrant City	KERNERSVILLE	Registrant State	NC
Registrant Zip Code	27284-9799	Country	UNITED STATES
Region	Eastern	Registrant Type	Partnership
Fract Owner		Certificate Issue Date	2004-05-13
Status	The Triennial Aircraft Registration form was mailed and has not been returned by the Post Office		

----- History 11 -----

Last Action Date	2004-05-13		
Registrant Name	PIEDMONT PARTNERS	Street	5809 KINGSWAY LN
Registrant City	KERNERSVILLE	Registrant State	NC
Registrant Zip Code	27284-9799	Country	UNITED STATES
Region	Southern	Registrant Type	Partnership
Fract Owner		Certificate Issue Date	2004-05-13
Status	N-Number Assigned and Registered		

----- History 12 -----

Last Action Date	2003-05-20		
Registrant Name	EQUIPMENT LEASING ASSOCIATES INC	Street	101 BENNOCH RD
Registrant City	STILLWATER	Registrant State	ME
Registrant Zip Code	04489	Country	UNITED STATES
Region	New England	Registrant Type	Corporation
Fract Owner		Certificate Issue Date	1983-12-30
Status	The Triennial Aircraft Registration form was mailed and has not been returned		

by the Post Office

----- History 13 -----

Last Action Date	2000-05-16		
Registrant Name	EQUIPMENT LEASING ASSOCIATES INC	Street	101 BENNOCH RD
Registrant City	STILLWATER	Registrant State	ME
Registrant Zip Code	04489	Country	UNITED STATES
Region	New England	Registrant Type	Corporation
Fract Owner		Certificate Issue Date	1983-12-30
Status	The Triennial Aircraft Registration form was mailed and has not been returned by the Post Office		

***** No Deregistered Data Found *****

***** No Reserved Data Found *****

***** No FAA Accidents/Incidents Found *****

***** No NTBS Accidents Found *****

***** No NTBS Pre 1982 Accidents Found *****

----- SDR 1 -----

Date Of Report	2017-10-20	Operator Control Number	PAIR20170731S3982
Date Of Occurrence	2017-07-31	Aircraft Registration	700Y
Aircraft Manufacturer	PIPER	Aircraft Group Code	PA23
Aircraft Manufacturer Model	PA23250	Aircraft Make Model Sequence	7102308
Air Carrier Name	Unknown	Air Carrier Operation Code	
Operation Type	G	Stage Of Operation	INSP/MAINT
Severity Factor		Air Transport Association Code	Wheel/Ski/Float
Precautionary Procedures	NONE	Nature Of Condition	OTHER
Segment	AIRFRAME	Descriptive Name Of Part	WHEEL
Defective Location On Aircraft	MLG	Failed Part Condition	CRACKED
Part Total Time	7,014	Part Total Time Since Overhaul	
Component Manufacturer		Component Manufacturer Model	
Component Manufacturer Number		Manufacturer Part Number	40131
Ata Code			

Remarks

WHILE REMOVING THE WHEEL FROM THE RIGHT MAIN LANDING GEAR FOR ANNUAL INSPECTION, THE AXLE NUT WAS BINDING. REMOVED ALL AIR FROM THE TIRE AND THE BINDING WAS RELEASED. FOUND THE WHEEL CRACKED WITH THREE OF THE SIX THREADED INSERTS THAT HOLD THE WHEEL HALVES TOGETHER BROKEN OUT.

----- SDR 2 -----

Date Of Report	2017-05-17	Operator Control Number	PAIR20170404S3761
Date Of Occurrence	2017-04-04	Aircraft Registration	700Y
Aircraft Manufacturer	PIPER	Aircraft Group Code	PA23
Aircraft Manufacturer Model	PA23250	Aircraft Make Model Sequence	7102308
Air Carrier Name	Unknown	Air Carrier Operation Code	
Operation Type	G	Stage Of Operation	INSP/MAINT
Severity Factor		Air Transport Association Code	Landing Gear Actuator
Precautionary Procedures	NONE	Nature Of Condition	FLUID LOSS
Segment	AIRFRAME	Descriptive Name Of Part	ACTUATOR
Defective Location On Aircraft	MLG	Failed Part Condition	CRACKED
Part Total Time	6,967	Part Total Time Since Overhaul	
Component Manufacturer		Component Manufacturer Model	
Component Manufacturer Number		Manufacturer Part Number	35032
Ata Code			

Remarks

PILOT REPORTED THE LEFT MAIN LANDING GEAR RETRACT/EXTEND ACTUATOR LEAKING. UPON INSPECTION FOUND THE ACTUATOR HOUSING TO BE CRACKED APPROXIMATELY .875 INCH LONG. THE HOUSING HAD EVIDENCE OF CORROSION IN THE CRACKED AREA WHICH WAS LOCATED UNDER THE NACELLE DUST BOOT. IT APPEARS THAT THE DUST BOOT HELD MOISTURE IN CONTACT WITH THE ACTUATOR HOUSING CAUSING THE CORROSION AND POSSIBLY CONTRIBUTING TO THE FORMATION OF THE CRACK.

----- SDR 3 -----

Date Of Report	1996-07-25	Operator Control Number	96ZZZX3696
Date Of Occurrence	1996-06-28	Aircraft Registration	700Y
Aircraft Manufacturer	PIPER	Aircraft Group Code	PA23
Aircraft Manufacturer Model	PA23250	Aircraft Make Model Sequence	7102308
Air Carrier Name	Unknown	Air Carrier Operation Code	

Operation Type	G	Stage Of Operation	INSP/MAINT
Severity Factor		Air Transport Association Code	Emergency Locator Beacon
Precautionary Procedures	NONE	Nature Of Condition	OTHER
Segment	COMPONENT	Descriptive Name Of Part	BATTERY
Defective Location On Aircraft	ELT	Failed Part Condition	LEAKING
Part Total Time		Part Total Time Since Overhaul	
Component Manufacturer	MERL	Component Manufacturer Model	CIR11
Component Manufacturer Number	23437	Manufacturer Part Number	BP1026
Ata Code			
Remarks	OPEN ELT BATTERY TO CHANGE BATTERY AND C/W FAR 91.207. FOUND BATTERY PACK LEAKING AND ELT ITSELF JUST STARTING TO CORRODE. SUSPECT CAUSE EITHER AGE OF HEAT FROM SUN. SUBMITTER RECOMMENDS TO KEEP COMPLYING WITH FAR 91-207.		

[Custom Reports](#)

Copyright 2001 - 2025 AviationDB.com Corp. All Rights Reserved

[Legal](#)[Contact Us](#)