

Piper PA-24 / PA-30 / PA-39

Applicable AD List

<u>AD Number</u>	<u>Subject</u>	<u>Effective Date</u>	<u>Applicable</u>	<u>SL / SB</u>	<u>Kit / Part No.</u>
<u>64-09-05</u>	Replacement of Alternate Air Doors	05/29/64	PA-30	<u>SB-220</u>	756 794
<u>64-16-06</u>	Replacement of Nose Gear Retraction Tube	08/20/64	PA-30	<u>SL-409</u>	21109-05
<u>64-21-05</u>	Governor - Replacement of Relief Valve Springs	09/16/64	PA-30	<u>HC-SB-61-88A</u>	A-3107
<u>64-28-03</u>	Removal of Restriction to Air Speed Limits	12/24/64	PA-30	<u>SB-222A</u>	756 827 / 22655-07
<u>65-11-04</u>	Modification of Pitch Servo	05/15/65	PA-30	<u>SB-224</u>	756 836, 837, 842 and 843
<u>66-18-04</u>	Baggage Door Latch	08/10/66	PA-24/30	<u>SL-478</u>	N/A
<u>66-28-06</u>	Removal of Restriction to Airspeed Limits	11/25/66	PA-30	<u>SB-229A</u>	755 044
<u>67-19-05</u>	Modification of Oxygen Cylinder Rear Retaining Strap	06/07/67	PA-30	<u>SB-246</u>	757 094 / 758 109
<u>69-13-03</u>	Prevent carbon monoxide from entering airplane cabin	12/14/73	PA-30	<u>SWHSM</u>	P/N 754-708
<u>69-24-04</u>	Reissued Airplane Flight Manual and New Placards	08/05/77	PA-30	<u>SB-301A</u>	760 354
<u>70-15-17</u>	Airspeed Limitation Placard	08/04/70	PA-30	N/A	N/A
<u>70-22-02</u>	Fuel Selector Valve Modification	11/04/70	PA-30	<u>SB-314A</u>	760 444
<u>70-22-05</u>	Alternator System Modification	11/30/71	PA-30	<u>SB-306</u>	760 347
<u>71-12-05</u>	Electric Trim Switch Modification	06/16/71	PA-24/30/39	<u>SB-331</u>	760 273, 760 309
<u>72-22-05</u>	Operation Limitation Placard	12/26/74	PA-24/30	<u>SL-687</u>	760 747
<u>74-13-03</u>	Stabilator Attach Bolts	04/30/76	PA-24/30/39	<u>SL-667A</u>	502 329, 502 342
<u>74-16-08</u>	Fuselage Aft Bulkhead Inspection	08/09/74	PA-30/39	<u>SL-679</u>	760 783
<u>75-05-02</u>	Engine Oil	02/21/75	PA-24/30	<u>SB-B-1-1-75-1</u>	N/A
<u>75-12-06</u>	Fin Forward Spar	06/05/75	PA-30	N/A	N/A
<u>75-27-08</u>	Torque Tube Bearing Fittings	06/03/76	PA-24/30/39	<u>SB-464A</u>	760 835 / 28216-02
<u>76-18-05</u>	Fin Front Spar Modification	09/10/76	PA-30/39	<u>SL-777</u>	N/A
<u>76-19-07</u>	Stabilator Weight Assembly	09/29/76	PA-24/30	<u>SB-496</u>	760 747 / 28035-00
<u>77-08-01</u>	Aileron Spar Cracks	04/18/77	PA-24/30/39	<u>SL-787</u>	760 914
<u>77-09-10</u>	Electric Trim Switch	05/12/77	PA-24/30/39	<u>SB-527</u>	760 505 / 756 047
<u>77-13-21</u>	Prevent Landing Gear Collapse	12/16/77	PA-24/30/39	<u>SL-782A/B</u>	760 627 / 761 082
<u>78-12-07</u>	Fuel Selector Valve Replacement	06/19/78	PA-30/39	<u>SB-597</u>	P/N 492 137 (1H7-8)
<u>79-12-08</u>	Fuel Valve Internal Leak Check	06/19/79	PA-30/39	<u>SL-851</u>	N/A
<u>79-20-10</u>	Aileron Nose Rib Inspection/Reinforcement	10/04/79	PA-24/30/39	<u>SL-850</u>	763 893 / 20213-00 / 20234-22

Piper PA-24 / PA-30 / PA-39

Applicable AD List

<u>AD Number</u>	<u>Subject</u>	<u>Effective Date</u>	<u>Applicable</u>	<u>SL / SB</u>	<u>Kit / Part No.</u>
<u>81-19-04</u>	Rajay Turbocharger Hose Assemblies	09/17/81	PA-30	<u>SL-28</u>	N/A
<u>82-23-01 R1</u>	Placard Near Flap Actuator	04/07/83	PA-24/30/39	<u>SB-19</u>	N/A
<u>83-10-01</u>	Stainless Steel Fuel Selector Valve Housing	06/15/83	PA-30/39	<u>SL-589</u>	757 187
<u>83-19-03</u>	Lower Spar Cap Inspection	09/30/83	PA-24/30/39	<u>SB-751</u>	21919-00,-01,-08,-09 / 21918-00,-01
<u>85-02-05 R1</u>	Piper P/N's 81090-02, 683-107 Placard Installation	11/21/97	PA-24/30/39	N/A	P/N 683-107
<u>91-21-09</u>	Air Induction System	11/29/91	PA-30	<u>SB-861</u>	P/N 760-516
<u>94-13-10</u>	Stabilizer Torque Tube	08/12/94	PA-24/30/39	<u>SB-411A</u>	N/A
<u>97-01-01 R1</u>	Main Gear Sidebrace Stud	12/08/98	PA-24/30/39	N/A	P/N 20829-00 / P/N 22512-00
<u>98-02-08</u>	Inspection of Crankshaft I.D. for Corrosion	03/30/98	PA-30	<u>SB-505B</u>	N/A
<u>98-21-21 R1</u>	Electric Inflatable Door Seals	05/01/00	PA-24/30	<u>BFA-001</u>	P/N BFA 1894-KIT / P/N BFA 54-1000
<u>99-05-09</u>	Induction Air Filter	03/19/99	PA-24/30	<u>SB-1022</u>	P/N 460-632
<u>99-14-01</u>	AFM Revision	08/17/99	PA-30/39	N/A	N/A
<u>2001-23-17</u>	Garmin GNS 430 units	12/28/01	PA-24/30	<u>SB-1036</u>	N/A
<u>2005-01-19</u>	Mode S transponders	02/23/05	PA-24/30	<u>SB-409</u>	P/N A00-10113-07
<u>2006-03-08</u>	Vacuum pumps	03/10/06	PA-24/30	<u>SB-05-01</u>	N/A
<u>2006-12-07</u>	ECI Cylinder Assemblies	07/11/06	PA-24/30	<u>MSB 05-8</u>	N/A
<u>2012-17-06</u>	Flight Controls	10/22/12	PA-24/30	<u>SB-1189</u>	P/Ns 22882-003, 20399-004, 20399-005
<u>2015-19-07</u>	AMOC to AD 2015-19-07	11/03/15	PA-30	<u>SB-342G</u>	N/A
<u>2015-24-05</u>	Fuel Warning Placard and POH Inspection	01/12/16	PA-24/30/39	<u>SB-1266</u>	N/A
<u>2017-15-05</u>	Supersedes AD 69-13-03	08/28/17	PA-30	N/A	N/A
<u>2017-16-11</u>	Connecting Rods w/ Non-Conforming Small End Bushings	08/15/17	PA-30	<u>SB-632B</u>	N/A
<u>2022-03-15</u>	Garmin G3X / GI 275 MED	03/21/22	PA-30	N/A	N/A
<u>2023-09-09</u>	V Band Couplings	07/17/23	PA-30/39	N/A	N/A
<u>2024-14-03</u>	Garmin GFC500 A/P System	08/20/24	PA-30/39	N/A	N/A