

Aircraft Logbook Audit



AIRCRAFT DESCRIPTION - NOTE AIRFRAME AND ENGINE TIMES ARE APPROXIMATE										
Year	Make	Model	Registration	Serial No.	AFTT	Engines	SMOH	MGTOW	Empty Wt	Useful Load
1964	Piper	PA30	N7387Y	30-442	3,996	IO-320-B1A	L-1006-55/L-988-55	3,600	2,310	1,290
Base Color	Trim 1	Trim 2	Trim3	Int Material		Annual Due	ELT Due	IFR Checks Due	ADS-B	Oil
Turquoise	White	Blue	8	Vinyl	Complete	9/30/26	5/31/28	Now	Out Only	Aeroshell 15W50
LOGBOOK	DATE	AFTT	CATEGORY		DETAILS					
Airframe Log 1	May-64	0	Airframe - Inspection		STANDARD airworthiness certificate issued					
	Nov-65	386	Airframe - Remove / Install		Installed Alcor EGT gauge, Alt Air Door kit per Piper SL 448					
	May-67	590	Airframe - Damage		Installed new LH flap, aileron, pitot tube, standoff, and tail skid. Installed new gear retract cable.					
	Sep-68	741	Airframe - Remove / Install		Installed strobe lights, see 337					
	Jul-70	962	Airframe - Remove / Install		Installed kit 760-373 stall horn kit and 760-444 fuel valve mod per SB 310 Par 2 and SB 314					
	Nov-71	1,311	Airframe - Mx / Repair		LH Main fuel cell repaired					
	Apr-72	1,437	Airframe - Mx / Repair		RH Aux fuel cell repaired					
	Mar-73	1,722	Airframe - Remove / Install		Installed C/R Powerplant conversion kit 760-368. Installed CDI and DG. See 337					
	May-74	2,183	Airframe - Remove / Install		Replaced stabilator bolts per SL 667A, Replaced LH aileron nose bulkhead per AD 74-10-3					
	Apr-76	2,770	Airframe - Remove / Install		Installed rebuilt RH Main fuel cell. Replaced cabin door trim.					
	Oct-77	3,134	Airframe - Remove / Install		Installed new LH Aux fuel cell					
	Apr-78	3,149	Airframe - Remove / Install		Installed new RH Aux fuel cell					
	Jan-79	3,187	AD - Compliance		CW AD 77-13-21 Part A. Installed Piper NLG spring kit					
	Jul-79	3,210	Airframe - Remove / Install		Installed kit 760-783 on Aft Bulkhead per SL 679					
Airframe Log 2	Sep-82	3,334	Airframe - Remove / Install		Installed 4 ea new seatbelts.					
	Jan-87	3,510	Airframe - Remove / Install		Installed Cleveland Brake Kit IAW STC SA428NE					
	Jun-87	3,520	Airframe - Mx / Repair		Installed MetCoAire Plastic Wing Tips IAW STC SA871WE. See 337					
	Sep-88	3,549	Instrument - Remove / Instal		Installed EI EGT gauge					
	Dec-88	3,560	Airframe - Mx / Repair		Treated entire aircraft with ACF 50 corrosion block					
	Apr-92	3,596	Airframe - Remove / Install		Installed K2U Stainless steel nacelle fairings IAW STC SA516GL. Installed Bogert Copper Battery cable kit IAW STC SA3531NM. Installed removable panels on aft					
	Jun-01	3,685	Airframe - Remove / Install		Installed all new fuel cells from F&FC. Retaped all seams and rivets. Repaired fuel selectors at WEBCO.					
	May-05	3,701	Airframe - Mx / Repair		Installed MLG wiring and cleaned rust from NLG retract rod					
	Aug-16	3,718	Airframe - Mx / Repair		Replaced lower nacelle skins. Installed Bogert copper cables IAW STC SA3531NM.					
	Apr-18	3,801	Airframe - Remove / Install		Installed two C8100-E Electric fuel pumps IAW STC SA00786SE (OH'd LH side 2019). Replaced flexible brake lines. Repaired fuel selector valves. Replaced manual shutoff for heater. Replaced all flexible fuel hoses for both engines.					
	Jun-19	3,832	Instrument - Remove / Instal		Installed GTN 480 (CNX 80), 2 G5s, GTX33ES, EI VA-1A-300, GMA245, and GTR200 comm. Fabricated and installed new aluminum instrument panel overlays. Installed Guardian Avionics iPad mini panel mount and power supply.					
	Feb-21	3,888	Airframe - Remove / Install		Installed SureFly ignition system this date. See 337					
	Mar-21	3,900	Airframe - Paint / Interior		Stripped, alodined, and painted with Sherwin Williams AcryGlo in the following colors: XXX. Reupholstered seats, headliner and side panels with grey leather. Painted plastic trim components to match. Installed customer supplied one-piece windshield. Gustavo Aldana, AeroPinter Guatemala					
	May-24	3,960	Airframe - Inspection		ELT check and installed new ELT battery, expires 9-20-28. CW AD 77-13-21 Par A and B by inspecting per SL 782A and replacing bungees. Cleaned and treated corrosion on inspection panels aft of MLG. Installed new shimmy damper IAW STC SA634NE. See 337. Installed used serviceable MLG wheels. CW AD 79-20-10 by installing kit 763 893 due to cracks found in bulkhead. Repetitive inspections no longer required. Installed new LH aileron control cable. Installed new battery master solenoid and new main battery. Marked fuel tanks for capacity. Installed Aerospace logic dual fuel flow instrument. See 337.					
	Sep-25	3,966	Airframe - Inspection		CURRENT ANNUAL: ELT battery test. Repaired sun visor. Replaced 2 spark plugs on RH engine. Installed plastic pocket on aft bulkhead.					
	May-26	3,979	Change - Hobbs / Tach		Upgraded GMA 245 to GMA 345 audio panel. Replaced LH tach with serviceable tach at 221.1 tach and 3978.9 AFTT. New tach time is 1101.6					
L Engine Log 1	Mar-73	0	Engine - Overhaul		Complete OH of engines at 1722 ETT. All steel parts magnafluxed, crankcase repaired, installed new 1/2" exhaust valves, new cam followers, new rings and					
L Engine Log 2	Jun-92	1,877	Engine - Mx / Repair		Repaired #4 cylinder and engine driven fuel pump.					

[illegible]