

73874

PA 30-442

Left.

THE
adlogTM

**AIRCRAFT
MAINTENANCE
RECORDKEEPING
SYSTEM**

LEFT

**PROPELLER
MAINTENANCE
RECORDS**



PROPELLER MAINTENANCE RECORDS

Log No. 2

Aircraft Registration No. N 9387Y

Propeller Manufacturer HARTZELL

Hub Model _____

Blade Design No. 7663-4

Hub Serial No. BE - 3523

Blade Serial No's.

1. B 81277

2. B 86163

3. _____

4. _____

Pitch Range:

High _____ Low _____

Feather _____ Reverse _____

Governor Manufacturer _____

Model No. _____

Serial No. _____

Date installed on aircraft _____

Time Between Overhauls (TBO) _____ Hours



If used on multi-engine aircraft:

Right Left

Front Rear

(All applicable information must be filled in)



DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
				TOTALS brought forward from previous page
9-14-77	3134:00		3134:00	Hadgell Bulletin C/w #31,98,104 & 118A. Prop. O. H. C/w AD77-12-06
9-31-81			3298:25	AD77-12-06 C/w BY PIEDMONT AVN. SER. INC.
7-26-85			3446:93	PIPER SB. NO. 805 & HARTZELL SB. NO. 142 C/w 40134 PIEDMONT AVN. SER. INC.
4-18-92	3596:00	462:00	3596:00	REINSTALLED PROP. S/N BG3523 AFTER C/W AD77-1206R2, AD90-02-23 HARTZELL SB118, SB164 ACCOMPLISHED BY PIEDMONT AVN. SER. INC W.O. NO. D872P DATED 11-18-91. Kumar A. Jander AEP2061012
12-2-02	3690.53			Completed 100hr inspection Philip L. Kallakman AEP1860369
				<div data-bbox="207 1096 354 1150" data-label="Text"> <p>N7387Y TACH 3701.01</p> </div> <div data-bbox="519 1108 649 1138" data-label="Text"> <p>DATE 5/1/05</p> </div> <div data-bbox="207 1201 1063 1264" data-label="Text"> <p>I certify that this propeller has been inspected in accordance with a annual inspection and was determined to be in a airworthy condition</p> </div> <div data-bbox="406 1260 836 1344" data-label="Text"> <p> Richard C. Taylor IA 245605224</p> </div>
				<div data-bbox="284 1474 795 1507" data-label="Text"> <p>N7387Y DATE 8-15-07 LEFT TACH 3709.55</p> </div> <div data-bbox="284 1528 1161 1579" data-label="Text"> <p>I certify that this propeller has been inspected IAW annual inspection and has been determined to be in airworthy condition.</p> </div> <div data-bbox="284 1600 901 1654" data-label="Text"> <p>Chris Comer 2329395107 IA </p> </div>
			SUB-TOTALS this page	
			TOTALS—Carry forward to next page	

