

Aircraft Details

Use the query results with caution

Over time registration numbers are assigned to different aircraft and diverse data stores with inconsistent data are being joined

[Back to Query Entry](#)

N Number: 7887Y

Last Action Date	2023-03-17		
Airworthiness Date	1966-01-19	Expiration Date	2027-09-30
Manufacturer_Name	PIPER	Model Name	PA-30
Registrant Name	ASKINS JACK C	Street	4327 BARNETT RD
Registrant City	WICHITA FALLS	Registrant State	TX
Registrant Zip Code	763102303	Country	UNITED STATES
Region	Southwestern	Registrant Type	Individual
Fract Owner		Certificate Issue Date	2014-09-24
Status	N-Number Assigned and Registered		
Serial Number	30-973	Aircraft Type	Fixed wing multi engine
Mode S Code	52530642	Year Mfr	1966
Aircraft Category	Land	Builder Certification	Type Certificated
Number Engines	2	Number Seats	6
Aircraft Weight	CLASS 1	Aircraft Cruising Speed	139
Airworthiness Classification	Standard	Approved Operation Codes	Normal
Engine Manufacturer	LYCOMING		
Engine Model Name	IO-320 SERIES	Engine Type	Reciprocating
Engine Horsepower/Thrust	0	Fuel Consumed	0.00

----- History 1 -----

Last Action Date	2020-05-05		
Registrant Name	ASKINS JACK C	Street	4327 BARNETT RD
Registrant City	WICHITA FALLS	Registrant State	TX
Registrant Zip Code	763102303	Country	UNITED STATES

Region	Southwestern	Registrant Type	Individual
Fract Owner		Certificate Issue Date	2014-09-24
Status	N-Number Assigned and Registered		
----- History 2 -----			
Last Action Date	2017-08-30		
Registrant Name	ASKINS JACK C	Street	4327 BARNETT RD
Registrant City	WICHITA FALLS	Registrant State	TX
Registrant Zip Code	763102303	Country	UNITED STATES
Region	Southwestern	Registrant Type	Individual
Fract Owner		Certificate Issue Date	2014-09-24
Status	First Notice for Registration Renewal		
----- History 3 -----			
Last Action Date	2014-09-24		
Registrant Name	ASKINS JACK C	Street	1100 BROOK AVE
Registrant City	WICHITA FALLS	Registrant State	TX
Registrant Zip Code	763015009	Country	UNITED STATES
Region	Southwestern	Registrant Type	Individual
Fract Owner		Certificate Issue Date	2014-09-24
Status	Second Notice for Registration Renewal		
----- History 4 -----			
Last Action Date	2014-09-05		
Registrant Name	REGISTRATION PENDING	Street	1100 BROOK AVE
Registrant City	WICHITA FALLS	Registrant State	TX
Registrant Zip Code	763015009	Country	UNITED STATES
Region	Southwestern	Registrant Type	Individual
Fract Owner		Certificate Issue Date	
Status	Registration pending		
----- History 5 -----			
Last Action Date	2012-01-13		
Registrant Name	TRONCOSO CARLOS A	Street	344 GRANITE WASH
Registrant City	CLINTON	Registrant State	OK
Registrant Zip Code	736013648	Country	UNITED STATES

Region	Southwestern	Registrant Type	Individual
Fract Owner		Certificate Issue Date	1989-08-26
Status	First Notice for Registration Renewal		
----- History 6 -----			
Last Action Date	2009-11-19		
Registrant Name	TRONCOSO CARLOS A	Street	344 GRANITE WASH
Registrant City	CLINTON	Registrant State	OK
Registrant Zip Code	73601-3648	Country	UNITED STATES
Region	Southwestern	Registrant Type	Individual
Fract Owner		Certificate Issue Date	1989-08-26
Status	First Notice for Re- Registration/Renewal		
----- History 7 -----			
Last Action Date	2009-10-20		
Registrant Name	TRONCOSO CARLOS A	Street	101 MAPLEWOOD DR
Registrant City	CLINTON	Registrant State	OK
Registrant Zip Code	73601-3653	Country	UNITED STATES
Region	Southwestern	Registrant Type	Individual
Fract Owner		Certificate Issue Date	1989-08-26
Status	The Triennial Aircraft Registration form was mailed and has not been returned by the Post Office		
----- History 8 -----			
Last Action Date	2006-09-22		
Registrant Name	TRONCOSO CARLOS A	Street	101 MAPLEWOOD DR
Registrant City	CLINTON	Registrant State	OK
Registrant Zip Code	73601-3653	Country	UNITED STATES
Region	Southwestern	Registrant Type	Individual
Fract Owner		Certificate Issue Date	1989-08-26
Status	N-Number Assigned and Registered		
----- History 9 -----			
Last Action Date	2004-12-16		
Registrant Name	TRONCOSO CARLOS A	Street	13601 GREEN VALLEY DR
Registrant City	OKLAHOMA CITY	Registrant State	OK
Registrant Zip Code	73120-8547	Country	UNITED STATES
Region	Southwestern	Registrant Type	Individual

Fract Owner		Certificate Issue Date	1989-08-26
Status	N-Number Assigned and Registered		
----- History 10 -----			
Last Action Date	2004-09-21		
Registrant Name	TRONCOSO CARLOS A	Street	4200 WEST MEMORIAL ROAD
Registrant City	OKLAHOMA CITY	Registrant State	OK
Registrant Zip Code	73120	Country	UNITED STATES
Region	Southwestern	Registrant Type	Individual
Fract Owner		Certificate Issue Date	1989-08-26
Status	The Triennial Aircraft Registration form was mailed and has not been returned by the Post Office		

----- History 11 -----			
Last Action Date	2001-09-18		
Registrant Name	TRONCOSO CARLOS A	Street	4200 WEST MEMORIAL ROAD
Registrant City	OKLAHOMA CITY	Registrant State	OK
Registrant Zip Code	73120	Country	UNITED STATES
Region	Southwestern	Registrant Type	Individual
Fract Owner		Certificate Issue Date	1989-08-26
Status	The Triennial Aircraft Registration form was mailed and has not been returned by the Post Office		

----- History 12 -----			
Last Action Date	1998-09-16		
Registrant Name	TRONCOSO CARLOS A	Street	4200 WEST MEMORIAL ROAD
Registrant City	OKLAHOMA CITY	Registrant State	OK
Registrant Zip Code	73120	Country	UNITED STATES
Region	Southwestern	Registrant Type	Individual
Fract Owner		Certificate Issue Date	1989-08-26
Status	The Triennial Aircraft Registration form was mailed and has not been returned by the Post Office		

***** No Deregistered Data Found *****

***** No Reserved Data Found *****

----- FAA Accident/Incident 1 -----

Occurrence Date	1995-06-12	Aircraft Make	PIPER
Aircraft Model	PA30	Damage	MINOR
Document Last Modified	2012-08-08		
Narrative	GEAR RETRACTED ON LANDING ROLL BY MISTAKE IS INDICATED.		

******* No NTBS Accidents Found *******

----- NTBS Pre 1982 Accident 1 -----

Occurrence Date	1978-10-14	Aircraft Make	PIPER
Aircraft Model	PA-30	Aircraft Serial Number	00000030-973
Damage	SUBSTANTIAL	Accident Location	LUMBERTON,NJ
Occurrences	GROUND- WATER LOOP- SWERVE GEAR COLLAPSED	Phase of Flight	LANDING - ROLL LANDING - ROLL
Causes	FAILED TO MAINTAIN DIRECTIONAL CONTROL UNFAVORABLE WIND CONDITIONS OVERLOAD FAILURE	Narrative	ACFT COLLIDED WITH WIND TEE AND TETRAHEDRON. RIGHT MAIN LANDING GEAR COLLAPSED. WIND GUST 30 KNOTS

----- SDR 1 -----

Date Of Report	2000-03-09	Operator Control Number	2000ZZZX564
Date Of Occurrence	2000-01-21	Aircraft Registration	7887Y
Aircraft Manufacturer	PIPER	Aircraft Group Code	PA30
Aircraft Manufacturer Model	PA30	Aircraft Make Model Sequence	7103002
Air Carrier Name	Unknown	Air Carrier Operation Code	M71R
Operation Type	G	Stage Of Operation	INSP/MAINT
Severity Factor		Air Transport Association Code	Propeller Blade Section
Precautionary Procedures	NONE	Nature Of Condition	UNKNOWN
Segment	PROPELLER	Descriptive Name Of Part	BLADE
Defective Location On Aircraft	PROPELLER	Failed Part Condition	MISOVERHAULED
Part Total Time	3,995	Part Total Time Since Overhaul	219
Component Manufacturer		Component Manufacturer Model	
Component Manufacturer Number		Manufacturer Part Number	
Ata Code			
Remarks	AIRCRAFT WAS IN GEAR UP LANDING IN 1995. PROPELLER WAS		

OVERHAULED BY KANSAS PROPELLER AND AVIATION. WO NR 1008.
SUBMITTER STATED DAMAGE IN PRELOAD SHOULD HAVE BEEN
REJECTED IN 1995.

[Custom Reports](#)

Copyright 2001 - 2026 AviationDB.com Corp. All Rights Reserved

[Legal](#)

[Contact Us](#)